STUDENT PROJECTS LABORATORY - LOCKOUT / TAGOUT [LOTO] PROCEDURE

ENERGY ISOLATION SPECIFICATION | ASSET: CNC-03 | TAG: HURCO-CNC-01

Hurco CNC Turning Center / Lathe

Authorized LOTO Personnel: Sr. Instructional Lab Supervisor (Max Wright) & Student Research Assistants (SRAs)

Notification Channel: Max Wright - Teams / Text Message | Zone: Zone 2: CNC Machining (CNC)

STEP 1 - NORMAL MACHINE SHUTDOWN PROCEDURE

Aux/Menu -> Utility Screen -> Shutdown Control on pendant, then Master Power to OFF (Left rear of machine).

STEP 2 - HAZARDOUS ENERGY SOURCES, MAGNITUDES & ISOLATION POINTS

Source #1: Electrical (240V AC 3-Phase)

Isolation Location: Breaker switch on wall behind machine.

Lockout Procedure: Turn wall breaker switch to OFF and apply LOTO padlock & tag.

Source #2: Pneumatic (80 PSI Compressed Air)

Isolation Location: Behind machine on wall.

Lockout Procedure: Turn red handle counterclockwise to OFF, open bottom filter bleed valve, and verify gauge reads 0 PSI.

STEP 3 - STORED / RESIDUAL ENERGY DISSIPATION

Bleed pneumatic filter bowl valve to 0 PSI and allow hydraulic accumulator pressure to bleed down.

STEP 4 - ZERO-ENERGY VERIFICATION ('TRY' STEP)

Verify master power switch and pendant controls do not boot machine; confirm air gauge reads 0 PSI.