STUDENT PROJECTS LABORATORY - LOCKOUT / TAGOUT [LOTO] PROCEDURE

ENERGY ISOLATION SPECIFICATION | ASSET: FAB-03 | TAG: 01166873

Tennsmith HBU48-16 Hand Brake & Industrial Metal Shear

Authorized LOTO Personnel: Sr. Instructional Lab Supervisor (Max Wright) & Student Research Assistants (SRAs)

Notification Channel: Max Wright - Teams / Text Message | Zone: Zone 5: Fabrication, Sheet Metal & Abrasive Finishing (FAB)

STEP 1 - NORMAL MACHINE SHUTDOWN PROCEDURE

Shear (ID: 01166873): Push red power button (Right front face). Tennsmith Brake: Lower bending leaf and release clamping handle.

STEP 2 - HAZARDOUS ENERGY SOURCES, MAGNITUDES & ISOLATION POINTS

Source #1: Mechanical (Tennsmith HBU48-16 Hand Brake) (300 Ft-Lbs Counterweight & Clamping Leaf)

Isolation Location: Handle / counterweight linkage & upper clamping jaws.

Lockout Procedure: Apply Chain and LOTO Lock around handle/counterweight area to prevent motion; place spacer stock beneath clamp jaws to relieve stored mechanical energy.

Source #2: Electrical (Industrial Shear - ID: 01166873) (240V AC)

Isolation Location: Right-side electrical switch box.

Lockout Procedure: Turn right-side electrical switch box lever to OFF and install LOTO lock; press black power button to verify zero energy.

STEP 3 - STORED / RESIDUAL ENERGY DISSIPATION

Place spacer stock beneath Tennsmith brake clamping jaws; wait for Shear mechanism to come to rest.

STEP 4 - ZERO-ENERGY VERIFICATION ('TRY' STEP)

Press black power button on Shear to verify zero electrical energy; verify Tennsmith chain lock prevents leaf motion.