STUDENT PROJECTS LABORATORY - LOCKOUT / TAGOUT [LOTO] PROCEDURE

ENERGY ISOLATION SPECIFICATION | ASSET: FAC-02 | TAG: FAC-AIR-02

Shop Compressed Air System & Distribution Drops

Authorized LOTO Personnel: Sr. Instructional Lab Supervisor (Max Wright) & Facility Maintenance

Notification Channel: Max Wright - Teams / Text Message | Zone: Zone 6: Facility & Infrastructure (FAC)

STEP 1 - NORMAL MACHINE SHUTDOWN PROCEDURE

Place compressor controller in OFF/STOP mode and close main receiver tank outlet ball valve.

STEP 2 - HAZARDOUS ENERGY SOURCES, MAGNITUDES & ISOLATION POINTS

Source #1: Electrical (240V / 480V 3-Phase)

Isolation Location: Compressor room wall disconnect switch.

Lockout Procedure: Pull wall disconnect lever to OFF and install LOTO padlock & tag.

Source #2: Pneumatic (125 PSI Receiver Tank & 80-100 PSI Distribution Header)

Isolation Location: Receiver tank isolation valve & manual blowdown drain.

Lockout Procedure: Close header valve, slowly open tank manual drain valve to bleed stored air pressure, and verify tank & manifold gauges read 0 PSI.

STEP 3 - STORED / RESIDUAL ENERGY DISSIPATION

Bleed air receiver tank and shop distribution drops completely to 0 PSI before servicing filters or regulators.

STEP 4 - ZERO-ENERGY VERIFICATION ('TRY' STEP)

Verify compressor start button is dead and all pressure gauges read 0 PSI.