STUDENT PROJECTS LABORATORY - LOCKOUT / TAGOUT [LOTO] PROCEDURE

ENERGY ISOLATION SPECIFICATION | ASSET: MAC-01 / MAC-02 / MAC-03 | TAG: 001

Bridgeport Series I Manual Knee Mills (#1, #2, #3 - Tags: 001, 002, 003)

Authorized LOTO Personnel: Sr. Instructional Lab Supervisor (Max Wright) & Student Research Assistants (SRAs)

Notification Channel: Max Wright - Teams / Text Message | Zone: Zone 1: Manual Machining (MAC)

STEP 1 - NORMAL MACHINE SHUTDOWN PROCEDURE

Turn power switch to middle OFF position (Top left front face).

STEP 2 - HAZARDOUS ENERGY SOURCES, MAGNITUDES & ISOLATION POINTS

Source #1: Electrical (240V AC)

Isolation Location: Switch box to the right of Mill on fence post.

Lockout Procedure: Pull switch box lever down to OFF and install LOTO padlock (from machine shop cage or welding room) through lever.

STEP 3 - STORED / RESIDUAL ENERGY DISSIPATION

Allow spindle and drive pulley assembly to coast to a complete stop.

STEP 4 - ZERO-ENERGY VERIFICATION ('TRY' STEP)

Press black power button and verify spindle does not power on when mill switch is toggled.