STUDENT PROJECTS LABORATORY - LOCKOUT / TAGOUT [LOTO] PROCEDURE

ENERGY ISOLATION SPECIFICATION | ASSET: SAW-05 | TAG: JET-DP-01

JET Industrial Floor Drill Presses

Authorized LOTO Personnel: Sr. Instructional Lab Supervisor (Max Wright) & Student Research Assistants (SRAs)

Notification Channel: Max Wright - Teams / Text Message | Zone: Zone 4: Cutting, Saws & Drilling (SAW)

STEP 1 - NORMAL MACHINE SHUTDOWN PROCEDURE

Toggle front main power switch OFF.

STEP 2 - HAZARDOUS ENERGY SOURCES, MAGNITUDES & ISOLATION POINTS

Source #1: Electrical (120V AC)

Isolation Location: 120V wall power cord.

Lockout Procedure: Unplug and secure male plug inside Rotating Electrical Plug Lockout box; wait for spindle coast-down.

Source #2: Mechanical (50 lbs Stored Spring Tension)

Isolation Location: Quill Return Spring housing (left side of head).

Lockout Procedure: Retract quill fully upward to top dead center before servicing.

STEP 3 - STORED / RESIDUAL ENERGY DISSIPATION

Wait for complete spindle stop; retract drill press quill fully upward to relieve spring tension.

STEP 4 - ZERO-ENERGY VERIFICATION ('TRY' STEP)

Toggle Drill Press power switch ON to verify zero electrical energy.