# STUDENT PROJECTS LABORATORY - LOCKOUT / TAGOUT [LOTO] PROCEDURE

**ENERGY ISOLATION SPECIFICATION | ASSET: WLD-03 | TAG: NC090435**

## Lincoln Power MIG 255C Welder

**Authorized LOTO Personnel: Sr. Instructional Lab Supervisor (Max Wright) & Student Research Assistants (SRAs)**

Notification Channel: Max Wright - Teams / Text Message | Zone: Zone 3: Welding & Thermal Processing (WLD)

## STEP 1 - NORMAL MACHINE SHUTDOWN PROCEDURE

Extinguish arc, toggle main power switch OFF (Front Panel Bottom Left), close shielding gas cylinder valve (Rear).

## STEP 2 - HAZARDOUS ENERGY SOURCES, MAGNITUDES & ISOLATION POINTS

Source #1: Electrical (240V AC)

Isolation Location: Wall switch box disconnect.

Lockout Procedure: Pull wall switch box lever down to OFF & install LOTO lock; WAIT 5 MINUTES for internal capacitors to dissipate.

Source #2: Pneumatic (Shielding Gas) (2,500 PSI Compressed Argon/CO2 (C25))

Isolation Location: Rear cylinder top valve & regulator.

Lockout Procedure: Turn bottle valve clockwise until all yellow, disconnect gas line, pull MIG trigger to purge lines, and verify regulator gauges read 0 PSI.

## STEP 3 - STORED / RESIDUAL ENERGY DISSIPATION

5-minute capacitor bleed wait + pull MIG trigger to purge residual gas line pressure & release wire drive roll tension.

## STEP 4 - ZERO-ENERGY VERIFICATION ('TRY' STEP)

Verify digital wire speed/voltage displays stay dark when power switch is toggled; confirm regulator gauges read 0 PSI.