STUDENT PROJECTS LABORATORY - LOCKOUT / TAGOUT [LOTO] PROCEDURE

ENERGY ISOLATION SPECIFICATION | ASSET: WLD-04 | TAG: PLASMA-CNC-01

CNC Plasma Table & Hand Plasma Station

Authorized LOTO Personnel: Sr. Instructional Lab Supervisor (Max Wright) & Student Research Assistants (SRAs)

Notification Channel: Max Wright - Teams / Text Message | Zone: Zone 3: Welding & Thermal Processing (WLD)

STEP 1 - NORMAL MACHINE SHUTDOWN PROCEDURE

Turn off CNC controller & plasma power supply switch, close compressed air drop valve.

STEP 2 - HAZARDOUS ENERGY SOURCES, MAGNITUDES & ISOLATION POINTS

Source #1: Electrical (240V AC)

Isolation Location: Wall disconnect switch behind plasma power supply.

Lockout Procedure: Pull wall disconnect switch lever to OFF and install LOTO padlock & tag.

Source #2: Pneumatic (100 PSI Shop Compressed Air)

Isolation Location: Wall air supply ball valve & filter/regulator.

Lockout Procedure: Close air supply ball valve, disconnect quick-connect airline, and bleed regulator to 0 PSI.

STEP 3 - STORED / RESIDUAL ENERGY DISSIPATION

Bleed residual compressed air from plasma supply filter/regulator until gauge reads 0 PSI.

STEP 4 - ZERO-ENERGY VERIFICATION ('TRY' STEP)

Attempt to power on plasma cutter and CNC controller; verify zero power and 0 PSI on air gauge.