

Isp Q&A

 **Q1: How to troubleshoot when [MI WRN] _MI_ISP_OnUnBindInputPort: isp dev0 chn1, port 0 not support or created appears?**

It should be that the corresponding dev channel port has not been created or enabled. You can view the debugging information to check whether it has been created or enabled.

 **Q2: What is the process of developing ISP to process images?**

The common practice is to use iqttool to adjust the image effect first, and then use the MI_ISP_API_CmdLoadBinFile interface to load the adjusted parameters into it.

 **Q3: In ISP auto exposure mode, which strategy is the priority to change the exposure gain?**

Refer to the AEPLainLongTBI of the AE module of the isp tuning document, you can set the gain priority. It should be noted that ExposureLimit will limit the parameters and need to be modified at the same time.

 **Q4: Use ISP_TOOL to flash NandFlash, and the error "Verify Fail at 0x000007" appears when burning IPL?**

Make sure that the serial port of the board is closed (enter debug under uboot; enter 11111 under kernel, disconnect the SSH connection to the board), and operate according to the sigdoc burning document. If an error is reported according to the document operation, check the File Area under Erase Device when burning the IPL. Sometimes it is necessary to erase the file storage area to succeed.