

Field Service Bulletin FSB-2025-03

Subject: intermittent compressor shutdown on AeroFlow X200 units. Severity: high. Issued: 12 May 2025.

Affected Units

This bulletin applies to AeroFlow X200 units manufactured between January 2025 and March 2025, serial number prefix X2-25A. Root cause analysis traced the fault to start relay component lot L-1142 (part SR-1142), which can stick under thermal load and trip the compressor.

Corrective Action

Certified technicians must install Relay Retrofit Kit RK-114 and update controller firmware to version 2.4.1 on all affected units. The retrofit takes approximately 40 minutes per unit.

Warranty Treatment

Repairs performed under this bulletin are covered at no charge for all affected serial numbers, regardless of the standard warranty term, when completed before 31 December 2026.