STEPPER MOTOR CONTROL


Unipolar Stepper Motors

Stepper motors are characterized as *bipolar* or *unipolar*. Bipolar stepper motors have four lead wires and require a total of eight drive transistors (i.e., two full H-bridges). Unipolar have an additional center-tap on each phase for a total of six lead wires. With the center-taps connected to a common voltage source, unipolar stepper motors can be controlled with four identical "switches", typically NPN or N-channel drive transistors (Figure 1). In conventional full-stepping mode, one motor phase is energized at a time resulting in minimum power consumption and high positional accuracy regardless of winding imbalance. Half-stepping control alternates between energizing a single phase and two phases simultaneously resulting in an eight-step sequence which provides higher resolution, lower noise levels and less susceptibility to motor resonance.

The desired drive waveforms are illustrated in Figure 1. The eight step drive sequence shown (steps 1 through 8) advances the stepper motor four full steps or eight half steps. Reversing the drive sequence (i.e., from step 8 towards 1) reverses the direction of rotation.

		STEP	TRANSISTORS			
			1	2	3	4
Phase A	3 1	1	ON	OFF	ON	OFF
	3	2	ON	OFF	OFF	OFF
	74	3	ON	OFF	OFF	ON
	Phase B	4	OFF	OFF	OFF	ON
		5	OFF	ON	OFF	ON
	٢.	6	OFF	ON	OFF	OFF
		7	OFF	ON	ON	OFF
+++	<u></u>	8	OFF	OFF	ON	OFF

Figure 1: Half-step switching sequence for unipolar stepper motor.



FULL-STEP SEQUENCE

STEP	Q1-Q4	Q2-Q3 TP0	Q5–Q8 TP1	Q6-Q7
1	ON	OFF	ON	OFF
2	ON	OFF	OFF	ON
3	OFF	ON	OFF	ON
4	OFF	ON	ON	OFF
1	ON	OFF	ON	OFF

HALF-STEP SEQUENCE

STEP	Q1-Q4 TP0	Q2-Q3 TP1	Q5-Q8 TP2	Q6–Q7 TP3
1	ON	OFF	ON	OFF
2	ON	OFF	OFF	OFF
3	ON	OFF	OFF	ON
4	OFF	OFF	OFF	ON
5	OFF	ON	OFF	ON
6	OFF	ON	OFF	OFF
7	OFF	ON	ON	OFF
8	OFF	OFF	ON	OFF
1	ON	OFF	ON	OFF

Figure 2: "Two-phase-on" full step and half-step switching sequence for bipolar stepper motor.

Bipolar Stepper Motors

Simplified to the bare essentials, a bipolar permanent magnet motor consists of a rotating permanent magnet surrounded by stator poles carrying the windings (figure 3). Bidirectional drive current is used and the motor is stepped by switching the windings in sequence. For a motor of this type there are three possible drive sequences.

The first is to energize the windings in the sequence AB/CD/BA/DC (BA means that the winding AB is energized but in the opposite sense). This sequence is known as "one phase on" full step or wave drive mode. Only one phase is energized at any given moment (figure 4a). The second possibility is to energize both phases together, so that the rotor always aligns itself between two pole positions. Called "two-phase-on" full step, this mode is the normal drive sequence for a bipolar motor and gives the highest torque (figure 2 and figure 4b). The third option is to energize one phase, then two, then one, etc., so that the motor moves in half step increments. This sequence, known as half step mode, halves the effective step angle of the motor but gives a less regular torque (figure 2 and figure 4c). For rotation in the opposite direction (counterclockwise) the same three sequences are used, except of course that the order is reserved. As shown in these diagrams the motor would have a step angle of 90°. Real motors have multiple poles to reduce the step angle to a few degrees but the number of windings and the drive sequences are unchanged.




Figure 3: Simplified representation of a bipolar permanent magnet

Figure 4a : Wave drive (one phase on)




Figure 4b: Two phase on drive




Figure 4c : Half step drive

