

REPORT CLASSIFICATION

Classification Type	Full Form Analysis
---------------------	--------------------

DATE / TIME

Date of Occurrence	2022-08
Local Time Of Day	0001-0600

PLACE

Locale Reference	Airport
Locale	ZZZ.Airport
State	US
Altitude - AGL	0

ENVIRONMENT

Flight Conditions	VMC
Light	Night

AIRCRAFT / EQUIPMENT X

ATC / Advisory - Tower	ZZZ
Aircraft Operator	Air Carrier
Make Model Name	B737-400
Crew Size	2
Operating Under FAR Part	Part 121
Flight Plan	IFR
Mission	Cargo / Freight / Delivery
Flight Phase	Takeoff / Launch
Route In Use	Vectors
Airspace - Class B	ZZZ

COMPONENT 1

Aircraft Reference	X
Aircraft Component	Elevator Feel System

Problem	Malfunctioning
---------	----------------

PERSON 1

Aircraft Reference	X
Location In Aircraft	Flight Deck
Reporter Organization	Air Carrier
Function - Flight Crew	First Officer
Function - Flight Crew	Pilot Flying
Qualification - Flight Crew	Air Transport Pilot (ATP)
Qualification - Flight Crew	Multiengine
Qualification - Flight Crew	Instrument
ASRS Report Number	1927709

PERSON 2

Aircraft Reference	X
Location In Aircraft	Flight Deck
Reporter Organization	Air Carrier
Function - Flight Crew	Captain
Function - Flight Crew	Pilot Not Flying
Qualification - Flight Crew	Air Transport Pilot (ATP)
Qualification - Flight Crew	Multiengine
ASRS Report Number	1928033

EVENTS

Anomaly	Aircraft Equipment Problem - Less Severe
Anomaly	Deviation / Discrepancy - Procedural - Published Material / Policy
Anomaly	Ground Event / Encounter - Ground Strike - Aircraft
Anomaly	Inflight Event / Encounter - Loss Of Aircraft Control
Detector - Person	Flight Crew
Were Passengers Involved In Event	No
When Detected	In-flight
Result - General	Flight Cancelled / Delayed
Result - General	Maintenance Action

ASSESSMENTS

Contributing Factors / Situations	Aircraft
Contributing Factors / Situations	Human Factors
Contributing Factors / Situations	Procedure
Primary Problem	Aircraft

NARRATIVE 1

As my Captain called v1 rotate, I rotated the aircraft and the flight controls felt very light almost unresponsive and after the nose started rotating abruptly. The aircraft controls started feeling normal around 500 ft. After post inspection we noticed scrape at the tail skid section of the aircraft. Some kind of malfunction of flight controls on elevator feel centering unit.

NARRATIVE 2

During the take off roll I "V1 rotate" several seconds later the aircraft pitched up abruptly. After being airborne the Pilot Flying stated that the flight controls had no feel. I briefly assumed control of the aircraft and noted that that control yoke had very little feedback. I then transferred the controls back to the First Officer. The post flight inspection revealed the paint had been scraped from the tail skid. Suspicion of tail strike upon rotation. Confirmed on post flight inspection. Upon further inspection of the aircraft's maintenance log it was found that the aircraft's elevator feel and centering unit had been recently written up as inoperative in the aircraft's maintenance log. I am suspect of the repair and the testing of the flight control system was preformed improperly, and the aircraft was released to line not airworthy. Entry was made to the aircraft's maintenance log. I do not see this event occurring as a result of any one individual. There may be some training issues involved with the performance of the individuals involved. I mainly see this as leadership issue within the management of the Company. Management has either, not recognized these serious safety issues, or they have corrective action they have chosen not to working to correct these quality control issues.

SYNOPSIS

First Officer reported as the Captain called V1 rotate, I rotated the aircraft and the flight controls felt very light, almost unresponsive and the nose started rotating abruptly. The aircraft controls started feeling normal around 500 ft. After post inspection we noticed scrape at the tail skid section of the aircraft.

B737 flight crew reported flight control issues while rotating for takeoff. Upon arrival at the destination airport it was discovered a tail strike had occurred and a previous write up included an inoperative elevator feel and centering unit.

