

REPORT CLASSIFICATION

Classification Type	Full Form Analysis
---------------------	--------------------

DATE / TIME

Date of Occurrence	2001-10
Local Time Of Day	1801-2400

PLACE

Locale Reference	Airport
Locale	ZZZ.Airport
State	US
Altitude - AGL	0

ENVIRONMENT

Light	Night
-------	-------

AIRCRAFT / EQUIPMENT X

Aircraft Operator	Air Carrier
Make Model Name	B737 Undifferentiated or Other Model
Crew Size	2
Operating Under FAR Part	Part 121
Flight Phase	Parked
Maintenance Status - Maintenance Items Involved	Repair
Maintenance Status - Maintenance Items Involved	Testing

COMPONENT 1

Aircraft Reference	X
Aircraft Component	Fuselage Skin

PERSON 1

Location Of Person	Company
Reporter Organization	Air Carrier
Function	Other: STRUCTURES ENGINEER

ASRS Report Number	527789
Callback	Attempted

PERSON 2

Location Of Person	Company
Reporter Organization	Air Carrier
Function	Other: ENGINEERING

PERSON 3

Location Of Person	Company
Reporter Organization	Air Carrier
Function	Other: ENGINEER DIRECTOR

EVENTS

Anomaly	Aircraft Equipment Problem - Critical
Anomaly	Deviation / Discrepancy - Procedural - FAR
Anomaly	Deviation / Discrepancy - Procedural - Maintenance
Anomaly	Deviation / Discrepancy - Procedural - Published Material / Policy
Detector - Person	Other Person
Result - General	Maintenance Action
Result - General	None Reported / Taken
Result - Aircraft	Aircraft Damaged

ASSESSMENTS

Contributing Factors / Situations	Aircraft
Contributing Factors / Situations	Chart Or Publication
Contributing Factors / Situations	Company Policy
Primary Problem	Company Policy

NARRATIVE 1

ON JUN/FRI/00, ENGINEERING SUBMITTED A MEMO TO ACR, 'PRESSURIZED FUSELAGE LIGHTNING STRIKE DAMAGE REPAIR -- REQUIREMENT FOR NDT INSPECTION,' REQUESTING DEFERMENT OF THE NDT PART 6, SECTION 51-00-00 FIGURE 3 INSPECTION FOR 24 HRS TO ALLOW CONTINUED REVENUE SVC. ON JUN/FRI/01, BOEING RAPID RESPONSE REPLIED TO

ACR STATING: 1) ACR CAN DELETE THE B737-700 SRM 53-00-01 REPAIR 13 REQUIREMENT TO ACCOMPLISH NDT INSPECTIONS IF THE DAMAGE IS LESS THAN 0.3125 INCH IN DIAMETER AND ADHERES TO THE FOLLOWING: A) IN THE CASE WHERE THE DAMAGE IS A SMALL BURN MARK OR PIT, INSTALLATION OF A RIVET PER THE B737-700 SRM 53-00-01 REPAIR 13, PARAGRAPH 4C IS CONSIDERED STRUCTURALLY SATISFACTORY. B) IN THE CASE WHERE THE DAMAGE IS ON THE SURFACE, THE DAMAGE CAN BE BLENDED OUT FOLLOWING THE SRM BLEND-OUT GUIDELINES. INSTALL A RIVET PER B737-700 SRM 53-00-01 REPAIR 13, PARAGRAPH 4C IF ALLOWABLE DAMAGE REMOVAL LIMITS ARE EXCEEDED. 2) IF THE DAMAGE EXCEEDS 0.3125 INCH DIAMETER OR IF THERE IS DISCOLORATION IN THE PAINT, THE B737-700 SRM 53-00-01 REPAIR 13 NDT INSPECTION SHOULD BE ACCOMPLISHED TO DETERMINE THE EXTENT OF DAMAGE OR A SRM CUTOUT REPAIR ACCOMPLISHED. ON OCT/MON/01, I AM SUBMITTING DEPICTING THE FOLLOWING ERRORS: 1) ACR ENGINEERING KNOWINGLY AND WILLINGLY REMOVED THE STATEMENT REGARDING, 'IF THERE IS DISCOLORATION IN THE PAINT, THE B737-700 SRM 53-00-01 REPAIR 13 NDT INSPECTION SHOULD BE ACCOMPLISHED TO DETERMINE THE EXTENT OF DAMAGE OR A SRM CUTOUT REPAIR ACCOMPLISHED.' 2) THE B737-700, 300, 500, AND 200 ARE VERY CLR THAT AN NDT CONDUCTIVITY INSPECTION MUST BE ACCOMPLISHED TO DETERMINE THE EXTENT OF DAMAGE REF B737-700 SRM 53-00-01-2 REPAIR 13, PARAGRAPH 4.A.(1)(A), B737-300/500 SRM 53-00-01-3 FIGURE 219, PARAGRAPH 1. THE DYE PENETRATE INSPECTION IS NOT AN ALTERNATIVE TO A CONDUCTIVITY TEST THAT DETERMINES A POSSIBLE CHANGE IN HEAT TREATMENT. THE DYE PENETRATION EXAMINATION USES THE LIQUID TO GO INTO A DEFECT THAT IS OPEN AT THE SURFACE OF THE PART, IE, CRACKS. THE B737-700 SRM 53-00-01-2 REPAIR 13, PARAGRAPH 4B(1)(B)(2) ALLOWS FOR THE DYE PENETRATION, AS AN ALTERNATIVE INSPECTION ON THE OUTER SKIN AFTER DAMAGE REMOVAL NOT TO DETERMINE EXTENT OF DAMAGE AS THE RA IMPLIES. THE B737-300/500 SRM STATES THE SAME REF B737-300/500 SRM 53-00-01-3 FIGURE 219, PARAGRAPH 2(B).

SYNOPSIS

A B737 STRUCTURE'S ENGINEER ALLEGES UPPER MGMNT KNOWINGLY CHANGED THE MANUFACTURER'S REQUIREMENT FOR A NON DESTRUCTIVE TEST ON SKIN DAMAGE.

