

REPORT CLASSIFICATION

Classification Type	Full Form Analysis
---------------------	--------------------

DATE / TIME

Date of Occurrence	2016-02
Local Time Of Day	1201-1800

PLACE

Locale Reference	Airport
Locale	ZZZ.Airport
State	US
Altitude - AGL	0

ENVIRONMENT

Light	Daylight
-------	----------

AIRCRAFT / EQUIPMENT X

Aircraft Operator	Air Carrier
Make Model Name	B737-800
Crew Size	2
Operating Under FAR Part	Part 121
Flight Plan	IFR
Mission	Passenger
Flight Phase	Parked
Maintenance Status - Records Complete	N
Maintenance Status - Required / Correct Doc On Board	N

COMPONENT 1

Aircraft Reference	X
Aircraft Component	Wing Leading Edge

COMPONENT 2

Aircraft Reference	X
--------------------	---

Aircraft Component

Airframe

PERSON 1

Aircraft Reference	X
Location In Aircraft	Flight Deck
Reporter Organization	Air Carrier
Function - Flight Crew	Captain
Qualification - Flight Crew	Air Transport Pilot (ATP)
ASRS Report Number	1333289
Human Factors	Communication Breakdown
Communication Breakdown - Party1	Flight Crew
Communication Breakdown - Party2	Maintenance
Callback	Completed

PERSON 2

Aircraft Reference	X
Location In Aircraft	Flight Deck
Reporter Organization	Air Carrier
Function - Flight Crew	First Officer
Qualification - Flight Crew	Air Transport Pilot (ATP)
ASRS Report Number	1334710
Human Factors	Communication Breakdown
Communication Breakdown - Party1	Flight Crew
Communication Breakdown - Party2	Maintenance

EVENTS

Anomaly	Aircraft Equipment Problem - Less Severe
Anomaly	Deviation / Discrepancy - Procedural - FAR
Anomaly	Deviation / Discrepancy - Procedural - MEL / CDL
Anomaly	Deviation / Discrepancy - Procedural - Published Material / Policy
Detector - Person	Flight Crew
When Detected	Pre-flight
Result - General	Maintenance Action

ASSESSMENTS

Contributing Factors / Situations	Aircraft
Contributing Factors / Situations	Logbook Entry
Contributing Factors / Situations	Manuals
Contributing Factors / Situations	Procedure
Primary Problem	Procedure

NARRATIVE 1

First Aircraft, FO (First Officer) found dent in leading edge of right wing with very sloppy, conspicuous repair. Noted in the damage log, but looked substandard and damaged.

Same plane, FO found undocumented 12 in crack in vapor barrier with very old and peeling speed tape. This crack was open and barrier crack edges were separated. Tape was worn off in parts and crack was visible. There was no item in the logbook. The crack had propagated upward and inward past the existing, undocumented crack repair. This crack was subsequently after reporting, aircraft was taken out of service, signed off as a new crack.

In summation reference this vapor barrier issue, we found undocumented maintenance on an aircraft. We found an aircraft flying in an un-airworthy condition after this undocumented aircraft was repaired and not documented. There is a current airworthiness directive on this subject. I have no idea how long this plane has been flying in this un-airworthy condition.

There were RII's (Required Inspection Items) not accomplished on this aircraft. This is documented by me with a post incident review of the [manual].

The next aircraft we were given had 2 issues. There was clear Mylar tape on the outside of the R-3 window. It was peeling off. Maintenance wanted to peel tape off and was not happy I requested an investigation. A Log entry was then made. Per another Mechanic, this tape was still required to keep window sealant in place during the cure process. The mechanics later acknowledged that had the tape been in fact peeled off and flown again, since the sealant was still tacky, the window would have been required replacing again.

The FO found on this aircraft as well an undocumented repair to the right wheel well vapor barrier. This repair appeared to be in acceptable condition. There was no TAC (Tracking and Control) item for this crack. A later, further inspection of the sign off, showed an incorrect repair reference to the GPM (General Procedures Manual) and not the SRM (Structural Repair Manual) as required, since the vapor barrier is a secondary

structural member. An FEA (Fleet Engineering Authorization) was required for this sign off and was not accomplished as far as I could find in my forensic [manual] search.

In summation, we found another undocumented repair to another aircraft. This aircraft came out of C-check the day prior. This crack was signed off that same day as a new crack. I found through an [manual] search that there were RII's not accomplished on the aircraft. This crack appeared to be signed off as a new crack without a required FEA. This alarming "2 aircraft in a row" finding, is a grave indication of significant malfeasance in our maintenance department and could or will lead to significant fines and/or hull loss.

CALLBACK 1

Reporter stated: The dent in the wing was poorly repaired, "Looks like to was done by some high school kid". Reporter also stated: The cracks in the Vapor Barrier is an ongoing issue. The Vapor Barrier is required to be inspected every 600 hours or every "B" check. These cracks are to be entered in the Track and Control (TAC) system and removed after the repair is accomplished. The reporter stated that the item is often removed before the repair is accomplished. The reported stated that the repairs, when accomplished, are not being repaired per the Structural Repair Manual. The reporter Stated that he has reported this in the past and that the FAA and Boeing are aware of the cracks in the Vapor Barriers.

NARRATIVE 2

[Report narrative contained no additional information.]

SYNOPSIS

A B737-800 had unreported damage to the Leading Edge of the RH wing and some undocumented cracks on the Vapor Barrier in the wheel well area.

