

REPORT CLASSIFICATION

Classification Type	Full Form Analysis
---------------------	--------------------

DATE / TIME

Date of Occurrence	1995-11
Local Time Of Day	0601-1200

PLACE

Locale Reference	Airport
Locale	SFO
State	CA
Relative Position - Distance Nautical Miles	0
Altitude - AGL	0

ENVIRONMENT

Light	Daylight
-------	----------

AIRCRAFT / EQUIPMENT X

Aircraft Operator	Air Carrier
Make Model Name	B737-200
Crew Size	2
Operating Under FAR Part	Part 121
Flight Plan	IFR
Mission	Passenger
Flight Phase	Other: Other

COMPONENT 1

Aircraft Reference	X
Aircraft Component	Fuselage Main Frame
Problem	Malfunctioning

PERSON 1

Reporter Organization	Air Carrier
-----------------------	-------------

Function	Other: Ground Crew
Qualification	Other: Other
ASRS Report Number	345802
Callback	Completed

PERSON 2

Reporter Organization	Air Carrier
Function	Other: Ground Crew
Qualification	Other: Other

PERSON 3

Reporter Organization	Air Carrier
Function - Flight Crew	Captain
Function - Flight Crew	Pilot Flying
Qualification - Flight Crew	Air Transport Pilot (ATP)

PERSON 4

Reporter Organization	Air Carrier
Function	Other: Ground Crew
Qualification	Other: Other
ASRS Report Number	346092

EVENTS

Anomaly	Aircraft Equipment Problem - Less Severe
Anomaly	Other: Unspecified
Detector - Person	Other Person
Result - General	None Reported / Taken

ASSESSMENTS

Primary Problem	Aircraft
-----------------	----------

NARRATIVE 1

THE SIT HERE AFFECTS APPROX 5 B737-200 ACFT. THE FIRST WAS BROUGHT IN FOR AN (CORROSION CHK) 'R' CHK ON NOV/XX/95 AND THE LAST WAS IN ON JAN/XX/96. THE PROB OCCURRED WHILE COMPLYING WITH AIRWORTHINESS DIRECTIVE 95- 12-17. THIS CALLS FOR REPLACEMENT OF CRACKED CHORD ANGLES AT STA 727 ON THE B737 ACFT. THE REPAIR FOR THIS IS SPECIFIED IN MAINT MANUAL AND BOEING DRAWING. OUR CREW WAS NEW TO THE

JOB AND ASKED FOR GUIDANCE AND ADVICE FROM ANOTHER CREW THAT HAD PREVIOUSLY ACCOMPLISHED THE REPAIR. THROUGH A MISCOM WE WERE INFORMED THAT TWO FASTENERS THAT WERE TRAPPED BENEATH STRUCTURE BE GROUND FLUSH AND NOT PICKED UP. ONE FASTENER WAS ON THE NEW CHORD AND ONE WAS ON AN EXISTING STIFFENER REMOVED FOR ACCESS. THE PRINT WE WERE GIVEN OF BOEING DRAWING FOR THE FIRST ACFT HAD A HAND WRITTEN NOTE TO THIS EFFECT WE WERE TOLD WAS FROM ENGINEERING. THIS INFO WAS PASSED ON, AND SUBSEQUENTLY APPROX FOUR OTHER ACFT WERE REPAIRED THE SAME WAY. ON AUG/THU/96, WHILE WORKING THE SAME JOB WE WERE MADE AWARE THAT THIS PROC WAS NOT APPROVED. THIS ACFT WAS REPAIRED PROPERLY, AND THE ENGINEERING DEPT WAS NOTIFIED OF THE SIT. THEY ARE CURRENTLY IN CONTACT WITH BOEING TO RECTIFY THE PROB ON THE PREVIOUS ACFT REPAIRED INCORRECTLY. CALLBACK CONVERSATION WITH RPTR REVEALED THE FOLLOWING INFO: RPTR STATED THAT THE GRINDING OFF OF THE BULK HEAD FASTENERS WAS NOT LEGALLY AUTH BY THE MANUFACTURER OF THE ACFT, BOEING. HOWEVER, SINCE THE OTHER END OF THE FASTENERS ARE COVERED BY A CASTING, THERE IS NO DANGER THAT THEY WILL FALL OUT AND CAUSE INTERFERENCE WITH OTHER PARTS. THEREFORE, THE RPTR'S COMPANY FLEET ENGINEER IS WORKING WITH BOEING TO OBTAIN AUTH FOR THE GRINDING OF THE FASTENERS COVERING ALL PAST AND FUTURE REPAIRS IN THE SAME MANNER. THIS PROC IS ACTUALLY SAFER THAN REMOVING ALL THE STRUCTURE NECESSARY TO UNCOVER THE OTHER END OF THE FASTENERS.

SYNOPSIS

MECH OF A B737-200 RPTS AN UNAUTH REPAIR TO 5 SAME MAKE AND MODEL ACFT.

