CNC Lathe CL-50 Maintenance Manual, Revision C.

Spindle care: Grease the spindle bearings every 200 operating hours using lithium complex grease NLGI 2. Do not over-grease; two pumps per bearing is sufficient.

Coolant system: Check coolant concentration weekly and keep it between 6 and 8 percent. Clean the chip tray at the end of every shift. Replace the coolant completely every 3 months.