

	QUALITY SYSTEM		FORM
	DOCUMENT #: 3.100.019.F02		LEVEL: 3
	Effective Date:	APPROVED JEsqueda , 9/30/2025, 4:14:39 PM	Revision #: 09
TITLE:	OUT-OF-SPECIFICATION (OOS) RE-TEST FORM		Page 1 of 5

OOS Number: OOS- 262098

Phase II

Section A – Sample Detail				
Sample Name:	GLP3R/Cagrilinitide	Re-Test Date:	15-Sep-2026	Original Result:
Name of Analyst who Performed Re-Test:	Prepping Analyst: Alex Saravia (ES), Andrew Carrillo (AC) Processing Analyst: Alex Saravia (ES), Abayomi Odugbesi (AO)	Sample ID:	Original test: ETX-260902-0505 Retest:	Re-Test Result:
Section B – Investigation and Root Cause				
Investigation	Is the test conducted in accordance with the same method /process?	☒ Yes ☐ No		SOP#: MICRO-SOP-5
	Is reagents (reference standards, solvent, etc.) stored in proper condition and not expired?	☒ Yes ☐ No		Lot #: TSB: Please see Consumables section under the submission on EagleTrax FTM: Please see Consumables section under the submission on EagleTrax
				Exp. Date: TSB: Please see Consumables section under the submission on EagleTrax FTM: Please see Consumables section under the submission on EagleTrax
	Equipment/Instruments Used:	Are they functional and calibrated/PM?	Calibration / PM due date	
	ISO 5 BSC E001316, ISO 5 BSC E001314	☒ Yes ☐ No	Jun 2027, Jun 2027	
	CR E001736	☒ Yes ☐ No	Dec 2026	
	Incubator E001356 (Sensor E001450)	☒ Yes ☐ No	Jan 2027, Feb 2027	
	Incubator E001034 (Sensor E001501)	☒ Yes ☐ No	Aug 2027, Feb 2027	
	Incubator E001031 (Sensor E001505)	☒ Yes ☐ No	Aug 2027, Feb 2027	
	Is the clean room facility certified?	☒ Yes ☐ No ☐ N/A		Certified due date: 31-Dec-2026
	Do the controls (i.e. positive, negative, C3, etc.) conform to the required standards?	☒ Yes ☐ No ☐ N/A		See Phase II Summary
	Do the environmental monitoring results conform to required standards?	☒ Yes ☐ No ☐ N/A		SOP#: See Phase II Summary
	System Performance Check (if applicable)	☒ Yes ☐ No ☒ N/A		
System Suitability RSD < 2% (PDA)	☐ Yes ☐ No ☒ N/A			
System Suitability RSD <10 % (QDA,CAD)	☐ Yes ☐ No ☒ N/A			



QUALITY SYSTEM

FORM

DOCUMENT #: 3.100.019.F02

LEVEL: 3

Effective Date:

APPROVED

JEsqueda , 9/30/2025, 4:14:39 PM

Revision #: 09

TITLE:

OUT-OF-SPECIFICATION (OOS) RE-TEST FORM

Page 2 of 5

OOS Number: OOS- 262098

Is the analyst trained to perform the test?

☒ Yes ☐ No

Are the Test Result Records Attached & Calculations Verified and Correct?

☒ Yes ☒ No

Does the processing method/ method set conform to the required specification?

☒ Yes ☐ No

Re-Testing from the same vial?

☒ Yes ☒ No ☐ N/A

Is formula worksheet provided and verified?

☒ Yes ☒ No

Section C – Evaluation of Laboratory Testing/Hypothesis Testing (if applicable)

☐ N/A☐ Re-injection of sample vial☐ Re-injection of original standard vial☐ Re-vialing of original working standard solution☐ Re-vialing of original working sample solution☐ Re-dilution of a working sample solution from the original stock☐ Re-dilution of a working standard solution from the original stock standard☒ Other: Retest of additional vials from same lot

Section D – Phase II Summary

All the analysts involved in the testing - the initial processing analyst (Alex Saravia), the processing analyst who performed the retest (Abayomi Odugbesi), the reading analyst who confirmed the initial positive result (Elysse Nioupin), and the analyst who prepped and read the retest (Andrew Carrillo) - were interviewed comprehensively. Their answers are recorded throughout this document.

INITIAL TEST UNDER SUBMISSION ETX-260902-0505:

All analysts involved in the prepping, processing, and reading of the initial sample – Alex Saravia and Elysse Nioupin – were interviewed comprehensively. Upon arrival, the sample was stored in accordance with the Client 's instructions. Analysts verified the integrity of the sample throughout both preparation and processing stages. No leaks or turbidity were observed at any point, verifying sample integrity. All reagents and supplies mentioned in the material section above were stored according to the suppliers ' recommendations, and their integrity was visually verified before utilization. Moreover, all reagents and supplies had valid expiration dates. The functionality of all equipment was confirmed by reviewing data generated by our comprehensive in-house continuous monitoring system. The cleanroom suite (CR 114) used for processing procedures comprises three interconnected sections: the innermost ISO 7 cleanroom (114B), which connects to the middle ISO 7 buffer room (114A), and then to the outermost ISO 8 anteroom (114). A positive air pressure system is maintained throughout the suite to ensure controlled, unidirectional airflow from 114B through 114A and into 114. The ISO 5 Biological Safety Cabinet (BSC) E001316, located in the innermost ISO 7 room, (114B), was used for initial sample processing steps. It was thoroughly cleaned and disinfected prior to each procedure in accordance with MICRO SOP-9 (Cleaning and Disinfecting Procedure for Microbiology). Additionally, BSC E001316 was certified and approved by both the Engineering and Quality Assurance teams. Initial sample processing was conducted in the ISO 5 BSC E001316 in the innermost ISO 7 room, (114B) by Alex Saravia on 04 Sep 2026 as per MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test).

	QUALITY SYSTEM		FORM
	DOCUMENT #: 3.100.019.F02		LEVEL: 3
	Effective Date:	APPROVED JEsqueda , 9/30/2025, 4:14:39 PM	Revision #: 09
TITLE:	OUT-OF-SPECIFICATION (OOS) RE-TEST FORM		Page 3 of 5

OOS Number: OOS- 262098

Phase II Summary (continued):

On 04 Sep 2026, the sample vials for ETX-260902-0505 were received from Sample Submissions and brought into the Sterile Microbiology lab following multi-stage disinfection with acidified bleach (minimum 10-minute contact time at each transfer boundary). In ISO 5 BSC E001316, the containers were aseptically opened, and membrane filtration was performed (3 vials filtered) as per MICRO-SOP-5. Media bottles were transferred into designated incubators E001356 and E001357. On 10 Sep 2026 (Day 6 of incubation), microbial growth was observed in 1 x 100mL TSB media bottle by analyst Elysse Nioupin and confirmed by supervisor Robin Seymour. The positive TSB bottle was submitted for Differential Staining and Microbial Identification under ETX-260910-0290, which definitively identified the isolate as Microbacterium sp. PM5 (Gram-positive rods). All concurrent negative controls for the membrane filtration method remained sterile (no growth).

Upon analyzing environmental monitoring results, no microbial growth was detected on operator personnel fingertip touch plates, settling plates, or ISO 5 BSC surface contact plates on the date of testing (04 Sep 2026), the date before (03 Sep 2026), or the subsequent testing date (08 Sep 2026). Weekly active air monitoring of ISO 8 Room 114 recovered 2 CFUs (ETX-260914-0487, identified as Corynebacterium ureicelerivorans and Mycobacterium grossiae), which differed in morphology and genus from the sample isolate and was physically isolated within the outermost ISO 8 anteroom. Monthly cleaning and disinfection of Suite CR114 was performed on 30 Aug 2026 per MICRO-SOP-9 with all H2O2 indicators passing. All other samples processed in the same testing session tested negative, ruling out cross-contamination.

During preliminary interview, the processing analyst noted a potential handling discrepancy during the resuspension of the lyophilized vials. In addition, the same sample lot (2608-216) had previously been submitted and passed sterility testing via ScanRDI under ETX-260807-0602. Based on these initial findings and to investigate whether the positive recovery was attributable to an inadvertent analyst handling error during resuspension, a Phase II investigation was initiated, and additional sample vials from the same lot were requested from the client for retesting.

	QUALITY SYSTEM		FORM
	DOCUMENT #: 3.100.019.F02		LEVEL: 3
	Effective Date:	APPROVED JEsqueda , 9/30/2025, 4:14:39 PM	Revision #: 09
TITLE:	OUT-OF-SPECIFICATION (OOS) RE-TEST FORM		Page 4 of 5

OOS Number: OOS- 262098

Phase II Summary (continued):

PHASE II RETEST UNDER SUBMISSION ETX-260914-0470:

In accordance with Phase II investigation procedures under Form 3.100.019.F02, additional sample vials from lot 2608-216 were submitted for retesting under submission ETX-260914-0470.

The retest sample was prepared by Andrew Carrillo on 14 Sep 2026 and processed by Abayomi Odugbesi on 15 Sep 2026 in accordance with MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test) via membrane filtration (60 gm filtered across 4 vials). The retest was conducted in certified ISO 5 BSC E001314 within cleanroom suite CR 114 following standard multi-barrier disinfection and strict aseptic technique. All culture media (FTM Lot 2567320, TSB Lot 2567280) and reagents (Fluid D Lot 687774, Bacteriostatic Water Lot NM7681) were within valid expiration dates. Media bottles were incubated in designated incubators E001356 and E001357. Negative controls were handled concurrently and remained sterile.

On 21 Sep 2026 (Day 06 of incubation), microbial growth was observed in 1 x 100mL TSB media bottle by analyst Andrew Carrillo and confirmed by supervisor Robin Seymour. The positive bottle was submitted for Microbial Identification under ETX-260921-0498. Confirmatory identification definitively identified the isolate as Microbacterium sp. PM5 (Gram-positive short rods), matching the identical species and strain designation (PM5), morphology (white shiny lawn growth), media selection (TSB), and incubation kinetics (Day 6) of the initial failure under ETX-260902-0505 (ETX-260910-0290). All other samples processed in the batch on 15 Sep 2026 tested negative.

EVALUATION OF RETEST FINDINGS & JUSTIFICATION OF PRIOR SCANRDI RESULT:

The successful replication of microbial recovery in the independent retest—conducted by a different processing analyst (Abayomi Odugbesi) and a different prepping/reading analyst (Andrew Carrillo)—conclusively refutes the preliminary hypothesis of analyst handling error during reconstitution. If the initial recovery had been an isolated artifact of analyst technique, the identical microorganism (Microbacterium sp. PM5) would not have been recovered on the identical incubation day in the retest.

Importantly, the investigation evaluated why the prior rapid ScanRDI sterility test conducted on this lot (ETX-260807-0602) yielded a passing result. In compounded parenteral products, microbial contamination is typically characterized by a heterogeneous, non-uniform distribution of microorganisms across individual containers, particularly when bioburden is present at very low concentrations. Under such low-level non-uniform contamination, random unit sampling naturally results in some vials containing zero viable cells—as occurred with the vials sampled for ScanRDI under ETX-260807-0602—while other vials from the same batch harbor low-level viable microorganisms. In addition, no method suitability was on file for ScanRDI with this specific formulation.

When low-level viable bioburden was introduced into the 14-day compendial USP <71> membrane filtration enrichment process, the microorganisms were successfully enriched and recovered in TSB on Day 6 in both independent testing events (ETX-260902-0505 and ETX-260914-0470), yielding the identical isolate (Microbacterium sp. PM5). Therefore, the passing ScanRDI result and the two failing USP <71> results are scientifically consistent with the non-uniform distribution of low-concentration microbial bioburden within the compounded lot. Consequently, inherent product contamination in Lot 2608-216 is confirmed. The initial failing result for ETX-260902-0505 is confirmed valid, the retest for ETX-260914-0470 is confirmed failing, and Lot 2608-216 fails USP <71> sterility requirements.



QUALITY SYSTEM

FORM

DOCUMENT #: 3.100.019.F02

LEVEL: 3

Effective Date:

APPROVED

Revision #: 09

TITLE:

OUT-OF-SPECIFICATION (OOS) RE-TEST FORM

JEsqueda , 9/30/2025, 4:14:39 PM

Page 5 of 5

OOS Number: OOS-262098

Has root cause
been identified?☒ Yes ☐ No

The most probable cause is:

Inherent product contamination in Lot 2608-216, confirmed by the replication of identical microbial recovery kinetics (Day 6 in TSB) and the identical strain (Microbacterium sp. PM5) in retest ETX-260914-0470. The discrepancy with the passing ScanRDI result (ETX-260807-0602) is scientifically attributed to non-uniform microbial distribution at low concentrations within the compounded batch. Original result confirmed valid.

Client Care notified:

Yes ☒ No ☐

Section E – Corrective and Preventive Action

Corrective Action(s):

Client Care notified of confirmed OOS sterility failure. Lot 2608-216 rejected.

OOS cause (select all)

- ☐ Equipment Error
☐ Procedure ☐ Analyst
☐ Training ☐ System
☒ External Phenomena
Inherent
☐ Other: Product

Preventive Action(s)

N/A - Failure is inherent to client product; all laboratory equipment, media, and aseptic controls conformed to approved procedures.

CAPA required:

- ☐ Yes, CAPA # N/A QYC
☒ No

FOLLOW-UP REQUIRED: ☐ Yes ☒ No

FOLLOW-UP DATE:

Section F – Acknowledgement and Closure

Prepared by:

Print Name:

Date:

08-Oct-2026

Reviewed by:

Print Name:

Date:

08-Oct-2026

Approved by (QA):

Print Name:

Date:

Table 1: Information for ETX-260902-0505 under investigation

Processing Analyst	Reading Analyst	Sample ID	Related Microbial ID	Media with microbial growth	Microbial ID
Alex Saravia	Elysse Nioupin	ETX-260902-0505	ETX-260910-0290	1 x 100mL TSB bottle	<i>Microbacterium sp. PM5</i> (Gram (+) rods)
Abayomi Odugbesi	Andrew Carrillo	ETX-260914-0470	ETX-260921-0498	1 x 100mL TSB bottle	<i>Microbacterium sp. PM5</i> (Gram (+) short rods)

Table 2: Environmental Monitoring from Processing Performed on 04Sep26

Environmental Monitoring (EM) Sampling Site	Frequency	Date (DDMMYY)	Analyst (Initials)	Day /Week(s)	Observation*	Environmental Monitoring Plate ETX ID	Microbial ID	Notes
Personnel EM Bracketing								
Personnel (Left Touch and Right Touch)	Daily	03Sep26	ES	Date Before Testing	No growth	N/A	N/A	None
Personnel (Left Touch and Right Touch)	Daily	04Sep26	ES	Date of Testing	No growth	N/A	N/A	None
Personnel (Left Touch and Right Touch)	Daily	08Sep26	ES	Date After Testing	No growth	N/A	N/A	None
Biological Safety Cabinet EM Bracketing Biological Safety Cabinet (BSC)								
Surface Sampling of ISO 5 (4 locations)	Daily	03Sep26	ES	Date Before Testing	No growth	N/A	N/A	None
Surface Sampling of ISO 5 (4 locations)	Daily	04Sep26	ES	Date of Testing	No growth	N/A	N/A	None
Surface Sampling of ISO 5 (4 locations)	Daily	08Sep26	ES	Date After Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	03Sep26	ES	Date Before Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	04Sep26	ES	Date of Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	08Sep26	ES	Date After Testing	No growth	N/A	N/A	None
Weekly Active Air Sampling Bracketing								
Active Air Sampling of Cleanrooms	Weekly	04Sep26	ISS	Week on Testing Date	2 CFU (ISO 8 114)	ETX-260914-0487	<i>Corynebacterium ureicelerivorans</i> <i>Mycobacterium grossiae</i>	None
Surface Sampling of Anteroom and Cleanroom Bracketing								
Surface Sampling of Cleanrooms	Weekly	04Sep26	ISS	Week on Testing Date	No growth	N/A	N/A	None