OOS Number: OOS- 262098

Phase II

Section A – Sample Detail					
Sample Name:	GLP3R/Cagrilinitide	**Re-Test Date:**	15-Sep-2026	**Original Result:**	Fail
Name of Analyst who Performed Re-Test:	Prepping: Andrew Carrillo (ANC) Processing: Ayomide Odugbesi (AOD) Reading: Andrew Carrillo (ANC)	**Sample ID:**	Original: ETX-260902-0505 Retest: ETX-260914-0470	**Re-Test Result:**	Fail

Section B – Investigation and Root Cause				
Investigation	Is the test conducted in accordance with the same method /process?	☑ Yes ☐ No	SOP#: MICRO-SOP-5	If the answer is NO to any of the investigation item(s), mark the item(s) with sequential number starting with one (1) and comment here: Not Applicable
	Is reagents (reference standards, solvent, etc.) stored in proper condition and not expired?	☑ Yes ☐ No	Lot #: TSB: Please see Consumables section under the submission on EagleTrax FTM: Please see Consumables section under the submission on EagleTrax	
			Exp. Date: TSB: Please see Consumables section under the submission on EagleTrax FTM: Please see Consumables section under the submission on EagleTrax	
	Equipment/Instruments Used:	Are they functional and calibrated/PM?	Calibration / PM due date	
	ISO 5 BSC E001316, ISO 5 BSC E001314	☑ Yes ☐ No	Jun 2027, Jun 2027	
	CR 114 (E001736), CR 115 (E001737)	☑ Yes ☐ No	Dec 2026, Dec 2026	
	Incubator E001356 (Sensor E001450) Incubator E001357 (Sensor E001449)	☑ Yes ☐ No	Jan 2027, Feb 2027 Jan 2027, Feb 2027	
	Incubator E001034 (Sensor E001501)	☑ Yes ☐ No	Aug 2027, Feb 2027	
	Incubator E001031 (Sensor E001505)	☑ Yes ☐ No	Aug 2027, Feb 2027	
	Is the clean room facility certified?	☑ Yes ☐ No ☐ N/A	Certified due date: 31-Dec-2026	
	Do the controls (i.e. positive, negative, C3, etc.,) conform to the required standards?	☑ Yes ☐ No ☐ N/A	See Phase II Summary	
	Do the environmental monitoring results conform to required standards?	☑ Yes ☐ No ☐ N/A	SOP#: See Phase II Summary	
	System Performance Check (if applicable)	☐ Yes ☐ No ☑ N/A		
	System Suitability RSD < 2% (PDA)	☐ Yes ☐ No ☑ N/A		
	System Suitability RSD <10 % (QDA,CAD)	☐ Yes ☐ No ☑ N/A		

OOS Number: OOS- 262098

	Is the analyst trained to perform the test?	☑ Yes ☐ No
	Are the Test Result Records Attached & Calculations Verified and Correct?	☐ Yes ☑ No
	Does the processing method/ method set conform to the required specification?	☑ Yes ☐ No
	Re-Testing from the same vial?	☐ Yes ☑ No ☐ N/A
	Is formula worksheet provided and verified?	☐ Yes ☑ No

Section C – Evaluation of Laboratory Testing/Hypothesis Testing (if applicable)

- ☐ N/A
- ☐ Re-injection of sample vial
- ☐ Re-injection of original standard vial
- ☐ Re-vialing of original working standard solution
- ☐ Re-vialing of original working sample solution
- ☐ Re-dilution of a working sample solution from the original stock
- ☐ Re-dilution of a working standard solution from the original stock standard
- ☑ Other: Retest of additional vials from same lot

Section D – Phase II Summary

All the analysts involved in the testing - the initial prepping analyst (Ishita Sharma), the initial processing analyst (Alex Saravia), the initial reading analyst (Elysse Nioupin), the retest prepping and reading analyst (Andrew Carrillo), and the retest processing analyst (Ayomide Odugbesi) - were interviewed comprehensively. Their answers are recorded throughout this document. This investigation was performed in accordance with MICRO-SOP-53, Sterility Test Out-of-Specification Investigation Procedure.

INITIAL TEST UNDER SUBMISSION ETX-260902-0505:
All analysts involved in the prepping, processing, and reading of the sample - Ishita Sharma, Alex Saravia, and Elysse Nioupin - were interviewed comprehensively. Their answers are recorded throughout this document. This investigation was performed in accordance with MICRO-SOP-53, Sterility Test Out-of-Specification Investigation Procedure.

Upon arrival, the sample was stored refrigerated in accordance with the Client's instructions. Prepping analyst - Ishita Sharma - and processing analyst - Alex Saravia - verified the physical integrity and packaging of the sample throughout both the preparation and processing stages. No leaks, cracks, or visible turbidity were observed at any point, verifying container integrity.

All reagents and supplies mentioned in the material section above were stored according to the suppliers' recommendations, and their integrity was visually verified before utilization. Moreover, all reagents and supplies had valid expiration dates. The functionality of all equipment was confirmed by reviewing data generated by our comprehensive in-house continuous monitoring system.

The cleanroom suite (CR 114) used for processing procedures comprises three interconnected sections: the innermost ISO 7 cleanroom (114B), which connects to the middle ISO 7 buffer room (114A), and then to the outermost ISO 8 anteroom (114). A positive air pressure system is maintained throughout the suite to ensure controlled, unidirectional airflow from 114B through 114A and into 114.

The ISO 5 Biological Safety Cabinet (BSC) E001316, located in the innermost ISO 7 room (114B), was used for sample processing steps. It was thoroughly cleaned and disinfected prior to each procedure in accordance with MICRO SOP-9 (Cleaning and Disinfecting Procedure for Microbiology). Additionally, BSC E001316 was certified and approved by both the Engineering and Quality Assurance teams. Sample processing was conducted in the ISO 5 BSC E001316 in the innermost ISO 7 room (114B) by Alex Saravia on 04Sep26 as per MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test).

On 04Sep26, the sample vials for ETX-260902-0505 were received from the Sample Submissions team and brought into the Sterile Microbiology lab. Upon arrival, each sample vial was sprayed with an acidified bleach disinfectant, placed into pre-disinfected bins, and allowed a 10-minute contact time.

The secondary disinfection happened in the ISO 8 anteroom (114), where the vials were again treated with acidified bleach and provided a 10-minute contact time before processing. Subsequently, the vials were moved into innermost ISO 7 cleanroom (114B). Inside this cleanroom, the processing analyst, Alex Saravia, performed a final disinfection step, allowing an additional 10-minute contact time. Once fully disinfected, the vials were transferred into the ISO 5 BSC E001316.

Inside the BSC, each container was aseptically opened, ensuring minimal exposure to the environment. The contents were then reconstituted with 2mL Bacteriostatic water per vial (each vial containing GLP3R/Cagrilinitide in 25mg/5mg concentration). Half the contents of each reconstituted vial was then dispensed directly from the container into sterile canisters placed on a vacuum manifold for membrane filtration. The sample was processed and tested as per MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test). Media bottles were transferred into incubators E001356 and E001357 to begin incubation.

OOS Number: OOS- 262098

Phase II Summary (continued):

On 10Sep26 (Day 6 of incubation), microbial growth was observed in one TSB (Tryptic Soy Broth) media bottle by analyst, Elysse Nioupin, and confirmed by Microbiology Lab Supervisor, Robin Seymour. The positive TSB bottle for ETX-260902-0505 was submitted for Differential Staining and Microbial Identification under ETX-260910-0290. Differential staining indicated the presence of Gram-positive rods. Definitive identification identified the isolate as Microbacterium sp. PM5 (Gram-positive rods).

The culture media utilized were within their expiry period. Negative control media bottles for the membrane filtration method were handled, processed, and incubated in the same manner as the test samples. No microbial growth was observed in the corresponding negative controls.

Environmental Monitoring (EM) Recoveries Review:

ISO 5 BSC and Personnel Evaluation:
Upon reviewing the environmental monitoring data associated with the sterility test, no microbial growth was detected on personnel monitoring plates (left- and right-hand touch plates for analyst Alex Saravia), settling plates, or ISO 5 BSC surface sampling plates within BSC E001316 on the date of testing (04Sep26), the preceding testing date (03Sep26), or the subsequent testing date (08Sep26). Therefore, the contemporaneous personnel and ISO 5 environmental monitoring results do not support processing personnel or the ISO 5 BSC as a potential source of the Microbacterium sp. PM5 detected in test sample ETX-260902-0505.

Cleanroom EM Evaluation:
Routine weekly surface sampling of Cleanroom Suite 114 performed on 04Sep26 demonstrated no microbial growth. Weekly active-air monitoring of the outermost ISO 8 Room 114 (CR 114) recovered 2 CFUs (ETX-260914-0487), identified as Corynebacterium ureicelerivorans and Mycobacterium grossiae. All of these cleanroom environmental isolates differed distinctly in genus and morphology from the product contamination isolate (Microbacterium sp. PM5). Considering the facility's layered disinfection program, controlled unidirectional airflow, physical segregation of the ISO 8 anteroom, and complete absence of contamination in the ISO 5 critical zone, these recoveries represent an isolated background event and are not considered a credible source of contamination for the test sample.

The absence of contamination on analyst glove plates and work-surface environmental monitoring plates collected on the date of testing indicates that there was no viable transfer of contaminants to the ISO 5 BSC. Additionally, the lack of contamination in other samples processed during the same testing session further demonstrates that the testing environment was operating in optimal condition.

The analysts confirmed full compliance with cleaning procedures as outlined in MICRO SOP-9 (Cleaning and Disinfecting Procedure for Microbiology) and MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test).

Monthly cleaning and disinfection of the outermost ISO 8 Anteroom, the middle ISO 7 Buffer room, the innermost ISO 7 cleanroom, and its containing ISO 5 BSCs for Cleanroom suite CR114 was performed on 16Aug26, as per MICRO-SOP-9 (Cleaning and Disinfecting Procedure for Microbiology). During both cleaning cycles, it was documented that all H2O2 indicators passed. This confirms the efficient monthly cleaning of all three parts of Cleanroom suite CR114.

Analyzing a 6-month sample history for Solyn LLC (E75000), this specific analyte "GLP3R/Cagrilinitide" has had no prior failures using USP <71> / EP 2.6.1 Sterility Test during this period.

To assess the potential for sample-to-sample contamination contributing to the positive results, a comprehensive review was conducted of all samples processed on the same day. All other samples processed by the analyst and other analysts that day tested negative. These findings suggest that cross-contamination between samples is highly unlikely.

Based on the observations outlined above, it is unlikely that the failing results were due to reagents, supplies, the cleanroom environment, the process, or analyst involvement. Consequently, the possibility of laboratory error contributing to this failure is minimal and the original result is deemed to be valid.

However, when investigating the lot history, it was discovered that the same lot (Lot 2608-216) had previously been submitted for ScanRDI sterility testing under ETX-260807-0602 and yielded a passing result. Based on this conflicting passing ScanRDI result for the same lot, the laboratory requested additional sample vials from the client for retesting under ETX-260914-0470 and initiated a Phase II investigation (CORP-FORM-22).

OOS Number: OOS- 262098

Phase II Summary (continued):

PHASE II RETEST UNDER SUBMISSION ETX-260914-0470:
In accordance with Phase II investigation procedures under CORP-FORM-22, following the laboratory's discovery of the prior passing ScanRDI result (ETX-260807-0602) during the sample history investigation, additional sample vials from lot 2608-216 were requested from the client and submitted for retesting under submission ETX-260914-0470.

The retest sample was prepared by Andrew Carrillo on 14Sep26 and processed by Ayomide Odugbesi on 15Sep26 in accordance with MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test) via membrane filtration (60 gm filtered across 4 vials). The retest was conducted in certified ISO 5 BSC E001314 within Cleanroom Suite 115 following comparable disinfection and strict aseptic technique to original testing. All culture media were within valid expiration dates. Media bottles were incubated in designated incubators E001356 and E001357. Negative controls were handled concurrently and remained sterile.

On 21Sep26 (Day 06 of incubation), microbial growth was observed in 1 x 100mL TSB media bottle by analyst Andrew Carrillo and confirmed by supervisor Robin Seymour. The positive bottle was submitted for Microbial Identification under ETX-260921-0498. Confirmatory identification definitively identified the isolate as Microbacterium sp. PM5 (Gram-positive short rods), matching the identical species and strain designation (PM5), morphology (white shiny lawn growth), media selection (TSB), and incubation kinetics (Day 6) of the initial failure under ETX-260902-0505 (ETX-260910-0290). All other samples processed in the batch on 15Sep26 tested negative.

Upon analyzing environmental monitoring results for the retest processing on 15Sep26, no microbial growth was detected on operator personnel fingertip touch plates, settling plates, or ISO 5 BSC surface contact plates on the date of testing (15Sep26), the preceding testing date (14Sep26), or the subsequent testing date (16Sep26). Weekly active surface monitoring of Cleanroom Suite 115 showed no growth; weekly active air sampling in the outermost ISO 8 cleanroom 115 recovered 9 CFUs (ETX-260923-0402), identified as Kocuria indica, Brevibacterium sp. CS2, Corynebacterium sp, Micrococcus luteus, Paracoccus yeei, Staphylococcus hominis, and Kocuria rhizophila. All of these environmental isolates differed distinctly in genus and morphology from the product contamination isolate (Microbacterium sp. PM5). The ISO 5 critical zones in BSC E001314 remained completely sterile (0 CFU) and in optimal control throughout testing, with positive pressure cascades preventing anteroom air ingress. (Refer to Table 1 for sample details, Table 2 for environmental monitoring from processing performed on 04Sep26, and Table 3 for environmental monitoring from processing performed on 15Sep26).

It was identified that the same sample lot (2608-216) had previously been submitted by the client for ScanRDI sterility testing under submission ETX-260807-0602 and yielded passing results. However, it is important to note that a review of the submission determined that no approved method suitability test was available to support the validity for microbial growth recovery using the ScanRDI method for this specific sample.

Furthermore, the discrepancy between the previous passing ScanRDI result and the current USP <71> sterility failure may be attributable to the non-homogeneous distribution of microbial contamination within the compounded batch. When microbial contamination is present at very low levels, microorganisms may not be uniformly distributed throughout the product, resulting in variability between samples collected from the same lot. Consequently, one aliquot may not contain contaminating microorganisms and yield an acceptable result, while another aliquot from the same batch may contain viable microorganisms and generate a positive sterility test result. Given the absence of a qualified method suitability study for the ScanRDI submission, the prior passing result cannot be considered directly comparable to the current USP <71> sterility test outcome.

However, the replication of microbial recovery in the independent retest - conducted by a different processing analyst (Ayomide Odugbesi) in a different cleanroom suite (Cleanroom Suite 115 vs. Suite 114) and a different prepping/reading analyst (Andrew Carrillo) - conclusively confirms that the microbial recovery was not an isolated laboratory anomaly, as the identical microorganism (Microbacterium sp. PM5) was recovered on the identical incubation day (Day 6) in the same media type (TSB) in both tests.

Therefore, inherent product contamination in Lot 2608-216 is confirmed, both the initial failing result for ETX-260902-0505 and the retest ETX-260914-0470 is considiered valid.

OOS Number: OOS- 262098

Has root cause been identified? ☑ Yes ☐ No	The most probable cause is: Inherent sample contamination within Lot 2608-216, supported by recovery of the same organism (Microbacterium sp. PM5) during retesting. The original USP <71> sterility failure was confirmed as valid.	Client Care notified: Yes ☑ No ☐

Section E – Corrective and Preventive Action

Corrective Action(s): N/A RS 21 Oct 2026	**OOS cause (select all)** ☐ Equipment Error ☐ Procedure ☐ Analyst ☐ Training ☐ System ☑ External Phenomena ☐ Other: N/A QYC 21Oct26
Preventive Action(s) N/A RS 21 Oct 2026	CAPA required: ☐ Yes, CAPA # N/A QYC 21Oct26 ☑ No
FOLLOW-UP REQUIRED: ☐ Yes ☐ No	FOLLLOW-UP DATE:

Section F – Acknowledgement and Closure

	Print Name:	Date:
Prepared by:	Qiyue Chen Digitally signed by Qiyue Chen DN: OU=Eagle Analytical Services, O=Strerie Lab, CN=Qiyue Chen, E=qchen@eagleanalytical.com Location: Houston, TX Date: 2026.10.22 11:32:05-05'00' Foxit PDF Editor Version: 13.2.7	16-Oct-2026
Reviewed by:	Robin Seymour Digitally signed by Robin Seymour DN: CN=Robin Seymour, O=Eagle Analytical Services, OU=Microbiology - Cleanroom Ops , E=rseymour@eagleanalytical.com Reason: I have reviewed this document Location: Date: 2026.10.22 13:08:04-05'00' Foxit PDF Editor Version: 14.0.8	22-Oct-2026
Approved by (QA):		

Table 1: Information for ETX-260902-0505 and ETX-260914-0470 under investigation

Processing Analyst	**Reading Analyst**	Sample ID	Related Microbial ID	Media with microbial growth	Microbial ID
Alex Saravia	Elysse Nioupin	ETX-260902-0505	ETX-260910-0290	1 x 100mL TSB bottle	*Microbacterium sp. PM5* (Gram (+) rods)
Ayomide Odugbesi	Andrew Carrillo	ETX-260914-0470	ETX-260921-0498	1 x 100mL TSB bottle	*Microbacterium sp. PM5* (Gram (+) short rods)

Table 2: Environmental Monitoring from Processing Performed on 04Sep26

Environmental Monitoring (EM) Sampling Site	**Frequency**	**Date (DDMMMYY)**	**Analyst (Initials)**	**Day /Week(s)**	**Observation***	**Environmental Monitoring Plate ETX ID**	**Microbial ID**	**Notes**
Personnel EM								
Personnel (Left Touch and Right Touch)	Daily	03Sep26	ES	Date Before Testing	No growth	N/A	N/A	None
Personnel (Left Touch and Right Touch)	Daily	04Sep26	ES	Date of Testing	No growth	N/A	N/A	None
Personnel (Left Touch and Right Touch)	Daily	08Sep26	ES	Date After Testing	No growth	N/A	N/A	None
Biological Safety Cabinet EM for E001316								
Surface Sampling of ISO 5 (4 locations)	Daily	03Sep26	ES	Date Before Testing	No growth	N/A	N/A	None
Surface Sampling of ISO 5 (4 locations)	Daily	04Sep26	ES	Date of Testing	No growth	N/A	N/A	None
Surface Sampling of ISO 5 (4 locations)	Daily	08Sep26	ES	Date After Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	03Sep26	ES	Date Before Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	04Sep26	ES	Date of Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	08Sep26	ES	Date After Testing	No growth	N/A	N/A	None
Weekly Active Air Sampling of Cleanroom Suite 114 (E001736) with Processing BSC								
Active Air Sampling of Cleanrooms	Weekly	04Sep26	ISS	Week of Testing	2 CFUs (ISO 8 114)	ETX-260914-0487	*Corynebacterium ureicelerivorans* *Mycobacterium grossiae*	None
Weekly Surface Sampling of Cleanroom Suite 114 (E001736) with Processing BSC								
Surface Sampling of Cleanrooms	Weekly	04Sep26	ISS	Week of Testing	No growth	N/A	N/A	None

Table 3: Environmental Monitoring from Processing Performed on 15Sep26

Environmental Monitoring (EM) Sampling Site	Frequency	Date (DDMMMYY)	Analyst (Initials)	Day /Week(s)	Observation*	Environmental Monitoring Plate ETX ID	Microbial ID	Notes
Personnel EM								
Personnel (Left Touch and Right Touch)	Daily	14Sep26	AOD	Date Before Testing	No growth	N/A	N/A	None
Personnel (Left Touch and Right Touch)	Daily	15Sep26	AOD	Date of Testing	No growth	N/A	N/A	None
Personnel (Left Touch and Right Touch)	Daily	16Sep26	AOD	Date After Testing	No growth	N/A	N/A	None
Biological Safety Cabinet EM for E001314								
Surface Sampling of ISO 5 (4 locations)	Daily	14Sep26	AOD	Date Before Testing	No growth	N/A	N/A	None
Surface Sampling of ISO 5 (4 locations)	Daily	15Sep26	AOD	Date of Testing	No growth	N/A	N/A	None
Surface Sampling of ISO 5 (4 locations)	Daily	16Sep26	AOD	Date After Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	14Sep26	AOD	Date Before Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	15Sep26	AOD	Date of Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	16Sep26	AOD	Date After Testing	No growth	N/A	N/A	None
Weekly Active Air Sampling of Cleanroom Suite 115 (E001737) with Processing BSC								
Active Air Sampling of Cleanrooms	Weekly	15Sep26	SMO	Week of Testing	9 CFUs (ISO 8 115)	ETX-260923-0402	*Kocuria indica* *Brevibacterium sp. CS2* *Corynebacterium sp* *Micrococcus luteus* *Paracoccus yeei* *Staphylococcus hominis* *Kocuria rhizophila*	None
Weekly Surface Sampling of Cleanroom Suite 115 (E001737) with Processing BSC								
Surface Sampling of Cleanrooms	Weekly	15Sep26	SMO	Week of Testing	No growth	N/A	N/A	None