




# Properties and Applications of Cast Iron

Presented by Dr Adijat 'Wumi Inyang

# Ferrous Metals

Ferrous Metals are sub-divided into categories:



# Fe – C phase diagram

**True equilibrium Fe – C phase diagram → 100% C = graphite**

Graphite formation promoted by

- Si > 1 wt%
- slow cooling

Instead of Fe<sub>3</sub>C





Fig. 13.2, Callister & Rethwisch 9e.  
[Adapted from *Binary Alloy Phase Diagrams*, T. B. Massalski (Editor-in-Chief), 1990. Reprinted by permission of ASM International, Materials Park, OH.]

# Fe – C phase diagram




**Cast irons = Carbon > 2.1wt% (typically 3-4.5wt%)**



# Fe – C phase diagram

**Cast irons = Carbon > 2.1wt% (typically 3-4.5wt%)**



# Cast Iron


---

- Ferrous alloys with  $> 2.1 \text{ wt\% C}$ 
  - more commonly  $3 - 4.5 \text{ wt\% C}$
- Low melting  $\sim 1300^\circ\text{C}$  – solidifies quickly on cooling  
= relatively easy to **cast** (earliest iron materials)
- Cementite decomposes to ferrite + graphite
$$\text{Fe}_3\text{C} \rightarrow 3 \text{ Fe } (\alpha) + \text{C (graphite)}$$
  - generally a slow process, promoted by  $> 1\text{wt\% Si}$

# Types of Cast Iron

---

There are 5 types of **cast iron**



- The type depends on the appearance of the microstructure
- The form that the graphite takes changes the properties
- In general, cast irons are often **brittle**

# Gray Cast Iron

## Microstructure:

- carbon = 2.5 – 4.0 wt%; silicon = 1.0 – 3.0 wt%
- graphite in the form of **flakes** in a pearlite or  $\alpha$ -ferrite matrix
- graphite weak and brittle in tension
- flakes act as stress concentration for brittle fracture
- Fracture surface reveals graphite, giving the gray appearance (so the name)

## Applications:

- stronger in compression
- excellent vibrational dampening
- wear resistant
- used in heavy machinery



20μm

Figs. 13.3(a), *Callister & Rethwisch 9e*.  
[Courtesy of C. H. Brady and L. C. Smith,  
National Bureau of Standards, Washington, DC  
(now the National Institute of Standards and Technology,  
Gaithersburg, MD)]




# Ductile Iron

## Microstructure:

- add Mg and/or Ce
  - graphite as nodules/spherelike not flakes
  - matrix often  $\alpha$  +  $\text{Fe}_3\text{C}$  (pearlite)
    - instead of ferrite  $\alpha$  (ferrite)
- depend on the heat treatment/cooling rate
- pearlite = stronger but less ductile
- ferrite matrix = ductile material
  - pearlite matrix = higher strength

## Applications:

- castings of valves and pumps
- crankshafts and gears
- machinery



Fully annealed at 700°C = ferrite matrix

Figs. 13.3 (b), *Callister & Rethwisch 9e*. [Courtesy of C. H. Brady and L. C. Smith, National Bureau of Standards, Washington, DC (now the National Institute of Standards and Technology, Gaithersburg, MD)]

# White Iron

## Microstructure:

- low Si content  $< 1$  wt% + fast cooling
- cementite microstructure (not graphite)  
= ferrite + pearlite
- very hard and brittle
- fracture surface appears white  
(so the name)
- slower cooling forms gray iron

## Applications:

- rollers for materials processing  
hard surface (fast cooling)  
more ductile inside (slower cooling)



Courtesy of Amcast Industrial Corporation  
Reprinted with permission of the  
Iron Castings Society, Des Plaines, IL

20μm

Figs. 13.3(c), *Callister & Rethwisch 9e*.


# Malleable Iron

## Microstructure:

- heat treat white iron at 800-900°C
- pearlite decomposes to graphite
- microstructure is then graphite in form of rosettes in ferrite matrix
- similar to nodular iron
- reasonably strong and ductile

## Applications:

- casings for automotive
- flanges and pipe fittings
- rail and marine engineering



Courtesy of Amcast Industrial Corporation  
Reprinted with permission of the  
Iron Castings Society, Des Plaines, IL

100μm

Figs. 13.3 (d), *Callister & Rethwisch 9e*.


# Compacted Graphite Iron

## Microstructure:

- Si content between 1.7 and 3.0 1 wt%  
carbon between 3.1 and 4 wt%
- graphite in 'worm-like' (or vermicular) shape
- less brittle than gray iron
- improved thermal conductivity
- good resistance to thermal shock
- lower oxidation at elevated temperatures

## Applications:

- diesel engine castings
- brake disc for high speed train
- flywheels



Courtesy of Sinter-Cast, Ltd.

Fig. 13.3(e), *Callister & Rethwisch 9e*.



# Properties of Cast Iron


Elastic modulus = 170 GPa (Fe 15% graphite)

| Type of cast iron  | Microstructure      | $\sigma_{UTS}$ / MPa | $\sigma_y$ / MPa | EL / % |
|--------------------|---------------------|----------------------|------------------|--------|
| Gray               | ferrite + pearlite  | 124                  | brittle          |        |
|                    | ferrite + pearlite  | 173                  |                  |        |
|                    | pearlite            | 276                  |                  |        |
| Ductile (nodular)  | ferrite             | 414                  | 276              | 18     |
|                    | pearlite            | 689                  | 483              | 3      |
|                    | tempered martensite | 827                  | 621              | 2      |
| Malleable iron     | ferrite             | 345                  | 224              | 10     |
|                    | ferrite + pearlite  | 448                  | 310              | 6      |
| Compacted graphite | ferrite             | 250                  | 175              | 3      |
|                    | pearlite            | 450                  | 315              | 1      |


Range of strength possible – mostly low ductility  
Material good for casting process

# Production of Cast Irons

Fig.13.5, *Callister & Rethwisch 9e*.  
(Adapted from W. G. Moffatt, G. W. Pearsall, and J. Wulff, *The Structure and Properties of Materials*, Vol. I, Structure, p. 195. Copyright © 1964 by John Wiley & Sons, New York. Reprinted by permission of John Wiley & Sons, Inc.)



# Summary of ferrous alloys



# Summary of ferrous alloys

---

## **Why are they so widely used?**

- Good properties
- Many years experience
- Abundant element on earth

## **Advantages:**

- Wide range of properties
- Stiff, strong and ductile
- Cheap to produce on large scale

## **Disadvantages:**

- Corrosion resistance is poor
- Relatively high density
- Poor electrical and thermal conduction