

Revised Ignition Coil for Repeated Misfire

Document: TSB-21-114

Type: Bulletin

Model: Falcon

Published: 2021-09-14

1 Condition

Some 2019-2021 Falcon vehicles with the 2.0T engine exhibit repeat misfire codes P0301 or P0300 after a coil has already been replaced.

2 Cause

The original ignition coil IC-2042-A insulation can degrade under repeated heat cycles, causing intermittent misfire that returns after replacement with the same part.

3 Repair Procedure

Replace all coils with revised ignition coil IC-2042-B, which supersedes IC-2042-A. Replace spark plug set SP-1108 if beyond half service life. Do not reinstall IC-2042-A from stock.

The connector failure mode is addressed by safety recall RC-2021-04.