

"Lumen 2.0T: EPS torque sensor fault causing intermittent steering assist los

Document: tsb-20-509

Area: bulletins

1 Condition

Drivers of the Lumen 2.0T may report a sudden, intermittent loss of power steering assist, with the steering wheel becoming heavy for a few seconds before assist returns. The event is usually logged as DTC C1556 in the EPS controller and may be accompanied by the EPS warning lamp. Capture freeze-frame data at the time of the fault to aid diagnosis. See the Lumen Steering Service Manual :: Steering System Overview for normal assist behavior.

2 Cause

DTC C1556 is set when the EPS controller detects an implausible or out-of-range signal from the torque sensor integrated into the electric power steering motor (EPS-8740). Internal contamination or a degraded sensor winding within the EPS-8740 assembly produces the intermittent dropout that triggers the temporary loss of assist. Reference the Lumen Steering Service Manual :: EPS Torque Sensor Fault for the code-setting criteria and the Lumen Steering Service Manual :: Electric Power Steering Motor for component detail.

3 Repair Procedure

Diagnose C1556 by verifying battery voltage, EPS connector integrity, and torque sensor signal per PROC-EPS-DIAG before replacing the electric power steering motor (EPS-8740) assembly. The torque sensor is not serviced separately, so a confirmed sensor fault requires replacing the complete EPS-8740 unit and performing the steering angle relearn afterward. Follow the full diagnostic flow in the Lumen Steering Service Manual :: Electric Power Steering Diagnosis Procedure , with the sub-system service context in the Lumen Steering Service Manual :: Electric Power Steering Sub-System Service . The complete code listing is in the Lumen Steering Service Manual :: Diagnostic Trouble Codes .