

"Vega 2.4: Lost communication with body control module on CAN bus"

Document: tsb-20-510

Area: bulletins

1 Condition

Some 2.4L Vega vehicles may exhibit intermittent or total loss of communication between the body control module and other modules on the high-speed CAN bus. When this occurs, DTC U0140 (Lost Communication With Body Control Module) sets as a current or stored fault, often accompanied by inoperative interior lighting, gauges, and power accessory functions. The condition may be temperature- or vibration-sensitive, making it difficult to reproduce on a stationary vehicle. Refer to the Vega Electrical Service Manual :: Network Communication Diagnostic Codes for the full list of related communication codes.

2 Cause

DTC U0140 is most commonly caused by an internal fault within the body control module BCM-9920, an open or high-resistance connection at the BCM connector, or a damaged CAN bus circuit between the BCM and the gateway. Corrosion at the module ground or a chafed harness can also intermittently interrupt communication. Review the operation described in Vega Electrical Service Manual :: Body Control Module and the symptom-specific diagnostic path in Vega Electrical Service Manual :: Lost Communication with BCM and Cluster before condemning BCM-9920.

3 Diagnosis

Before replacing any module, perform the published bus integrity test PROC-COMMS-DIAG to confirm whether the fault lies in the network wiring or within the body control module itself. Measure CAN-High and CAN-Low resistance and verify proper termination, then check for power and ground at the BCM-9920 connector. If the bus checks within specification but U0140 remains, the module is the likely failure. The complete procedure is documented in Vega Electrical Service Manual :: CAN Bus Communication Diagnosis Procedure .

4 Repair Procedure

If diagnosis isolates the fault to the module, replace body control module BCM-9920 and perform the configuration routine PROC-BCM-CONFIG to program the new module to the vehicle. Failure to complete configuration will leave the BCM-9920 unable to learn vehicle options and may cause U0140 to reset. Verify all accessory functions and confirm no communication codes return after a road test. Follow the detailed steps in Vega Electrical Service Manual :: Body Control Module Configuration Procedure and reference the broader Vega Electrical Service Manual :: BCM Sub-System Service section as needed.