

"Heron 2.5: Rough idle and P0352 caused by failed ignition coil B"

Document: tsb-22-308

Area: bulletins

1 Condition

Certain Heron 2.5 vehicles may exhibit a rough idle, intermittent misfire, and an illuminated MIL with DTC P0352 (Ignition Coil "B" Primary/Secondary Circuit) stored in the PCM. The condition is most noticeable during cold start and light-load cruise, and may be accompanied by a perceptible loss of power. Confirm the complaint by retrieving stored and pending codes; if P0352 is present on its own, follow this bulletin rather than performing a full circuit teardown. For background on how this code is set, refer to the Heron Ignition Service Manual :: Coil Primary and Secondary Circuit Faults .

2 Cause

The root cause has been traced to a manufacturing defect in early-production ignition coil B, part number IC-2044-A, in which the secondary winding insulation degrades under thermal cycling. As the insulation breaks down, the coil can no longer sustain a consistent spark event on cylinder 2, setting P0352 and producing the rough idle complaint. This is an application-specific coil; do not substitute a coil from another driveline. See Heron Ignition Service Manual :: Application-Specific Coils for the correct coil-to-application matrix and the broader Heron Ignition Service Manual :: Ignition Coils overview.

3 Repair Procedure

Replace ignition coil B (IC-2044-A) following PROC-IGN-COIL and inspect the corresponding spark plug SP-1110 for fouling or electrode wear while access is available. If the spark plug shows abnormal deposits, replace it per the specifications in Heron Ignition Service Manual :: Spark Plug Selection and Specifications . Torque and removal steps for the coil are detailed in the Heron Ignition Service Manual :: Ignition Coil Replacement Procedure . After installation, clear P0352 and verify no misfire counts accumulate; if the code returns, perform full circuit diagnosis per the Heron Ignition Service Manual :: Ignition Circuit Diagnosis .