

"Marlin EV: Front brake hose internal restriction causes uneven braking; insta

Document: tsb-25-305

Area: bulletins

1 Condition

Some Marlin EV vehicles may exhibit uneven braking, a slight pull, or a soft pedal that recovers after several seconds. The symptom traces to an internal restriction in an original-production front brake hose, which limits hydraulic flow and pressure release at one corner. The corrected service part is brake hose BH-7745. General orientation on the affected circuit is available in the Marlin EV Brakes Service Manual .

2 Cause

Affected front brake hoses can develop an internal liner flap that intermittently obstructs fluid flow under heavy braking. Because the restriction is internal, the hose passes a visual inspection and the condition is confirmed only by the uneven braking symptom. Replacement hose BH-7745 incorporates a revised liner that eliminates the flap. The hydraulic routing for this circuit is detailed in the Marlin EV Brakes Service Manual :: Hydraulic Lines and Fluid .

3 Repair Procedure

Replace the affected front brake hose with BH-7745 following procedure PROC-BRAKE-HOSE as described in the Marlin EV Brakes Service Manual :: Brake Hose Replacement Procedure . After the hose is installed, perform a full flush and bleed with fluid BF-7790 per procedure PROC-BRAKE-FLUID, referencing the Marlin EV Brakes Service Manual :: Brake Fluid Flush and Bleed Procedure . Confirm a firm pedal and even braking on a road test before returning the vehicle. Torque all fittings to specification listed in the Marlin EV Brakes Service Manual .