

"Vega 2.4: Front brake judder from warped rotors; replace BR-7731 and BP-7720"

Document: tsb-25-314

Area: bulletins

1 Condition

Some Vega 2.4 vehicles may exhibit a pulsation or judder felt through the brake pedal and steering wheel during moderate-to-firm braking from highway speeds. The condition is caused by lateral runout and thickness variation in the front brake rotors, part number BR-7731. Customers typically notice the judder intensifying as the rotors heat up during repeated stops. See the Vega Brakes Service Manual :: Front Brake Sub-System for the front corner layout.

2 Cause

The judder originates from disc thickness variation developing in front rotors BR-7731, accelerated by uneven pad transfer film and high-heat duty cycles. Once measurable runout exceeds the service limit, machining is no longer recommended and rotor replacement is required. The Vega Brakes Service Manual :: Front Brake Pad and Rotor Service lists runout and minimum thickness specifications, and the Kestrel Brakes Service Manual :: Brake System Overview describes comparable rotor wear patterns on the related platform.

3 Repair Procedure

Replace both front rotors, part number BR-7731, and the front brake pads, part number BP-7720, as a matched set following the Vega Brakes Service Manual :: Front Brake Pad and Rotor Service (PROC-BRAKE-FR). Do not machine the new rotors; install them dry and clean per the Vega Brakes Service Manual :: Front Brake Pad Replacement and bed the pads with a controlled burnishing sequence. After service, road test to confirm the judder is eliminated and inspect for even pad contact. Refer to the analogous Marlin EV Brakes Service Manual :: Front Brake Pad and Rotor Service Procedure for bedding technique on platforms sharing this caliper family.