

Osprey torque converter clutch stuck off causing shudder and TCC code

Document: tsb-26-113

Area: bulletins

1 Condition

Affected Osprey vehicles may set DTC P0741 (Torque Converter Clutch Circuit Performance or Stuck Off) accompanied by a noticeable shudder during light acceleration and elevated highway RPM. The torque converter clutch fails to lock up because solenoid TSOL-9520 is not commanding apply pressure. Confirm the complaint with a road test and scan data before teardown, and review the Transmission System Overview for normal TCC operation. The Diagnostic Trouble Code Reference section describes the P0741 set criteria.

2 Cause

The condition is caused by the torque converter clutch solenoid TSOL-9520 sticking in the off position, frequently aggravated by degraded or contaminated transmission fluid TFLT-9500 that varnishes the solenoid valve. The restricted fluid path prevents the solenoid from achieving clean apply pressure, producing the P0741 fault. Refer to the Torque Converter Clutch Diagnosis and the Fluid Pressure Diagnosis to confirm whether TSOL-9520 or fluid condition is the dominant factor.

3 Repair Procedure

Begin with a Fluid Level and Condition Inspection to evaluate transmission fluid TFLT-9500 for varnish or contamination. Perform PROC-SHIFT-SOL to replace the stuck solenoid TSOL-9520 following the Shift Solenoid Pack Replacement Procedure in the Shift Control Sub-System . Complete PROC-TRANS-SERVICE to flush and refill TFLT-9500 per the Transmission Fluid and Filter Service Procedure . Clear P0741, road test to confirm the TCC now locks up smoothly with no shudder.