

"Harrier 3.0 TD: Engine over-temperature from water pump seal weep"

Document: tsb-27-105

Area: bulletins

1 Condition

Owners of the Harrier 3.0 TD may report coolant loss, an over-temperature warning, or an illuminated MIL with DTC P0217 (Engine Over-Temperature Condition) stored. In some cases DTC P0128 (Coolant Thermostat Below Regulating Temperature) is also present if the thermostat has been disturbed during prior service. A pink coolant residue trail behind the front cover indicates seepage from the water pump weep hole. Review the code-setting logic in Harrier Cooling Service Manual :: Thermostat and Temperature Faults before condemning any part.

2 Cause

The P0217 over-temperature condition is caused by a failing internal seal in water pump WP-6122, which allows coolant to weep and progressively reduces flow through the engine. As coolant level drops, circulation degrades and engine temperature climbs beyond the protection threshold. If thermostat TSTAT-6100 was previously replaced with an incorrect opening temperature, it can compound the condition by delaying coolant flow. Confirm the leak source against Harrier Cooling Service Manual :: Coolant Circulation and verify WP-6122 part eligibility using Harrier Cooling Service Manual :: Water Pump Identification and Supersession .

3 Repair Procedure

Replace water pump WP-6122 following PROC-WATER-PUMP as detailed in the Harrier Cooling Service Manual :: Water Pump Replacement Procedure . Inspect thermostat TSTAT-6100 and replace it if the opening temperature is out of specification, referring to the Harrier Cooling Service Manual :: Thermostat Replacement Procedure . Refill and bleed the system per Harrier Cooling Service Manual :: Temperature Regulation , then clear P0217 and verify normal operating temperature on a road test. Additional component locations are documented in the Harrier Cooling Service Manual .