

"Vega EV-180: Lost communication with body control module on CAN bus"

Document: tsb-27-108

Area: bulletins

1 Condition

Affected Vega EV-180 vehicles may exhibit intermittent or total loss of communication with the body control module, setting DTC U0140 (Lost Communication with Body Control Module). Symptoms include inoperative interior lighting, non-responsive lock and unlock functions, and an instrument cluster that fails to display body status messages. Refer to Network Communication Diagnostic Codes for the full code description and the Lost Communication with BCM and Cluster subsection for symptom correlation before proceeding.

2 Cause

This condition is caused by an internal microcontroller fault in body control module BCM-9920 that intermittently drops the module off the high-speed CAN bus, triggering U0140 at the gateway and dependent nodes. The fault is heat-sensitive and may not reproduce until the module reaches operating temperature. Background on the affected component and its bus role is provided in the Body Control Module topic within the Electrical System Overview .

3 Repair Procedure

First confirm bus integrity by running PROC-COMMS-DIAG and the CAN Bus Communication Diagnosis Procedure to rule out wiring and termination faults before condemning the module. If the bus is healthy, replace body control module BCM-9920 and complete configuration per PROC-BCM-CONFIG using the Body Control Module Configuration Procedure . Additional service context for the module is documented under BCM Sub-System Service . After repair, clear U0140 and verify communication is restored across all body functions.