

"Falcon 2.0T: Low system voltage from failed 180A alternator"

Document: tsb-27-109

Area: bulletins

1 Condition

Affected Falcon 2.0T vehicles may set DTC P0562 (System Voltage Low) alone or together with P0620 (Generator Control Circuit) under electrical load. Drivers may report dimming headlamps, a battery warning indicator, and hard starting after extended idle. Confirm the codes against the System Voltage Codes and Generator Control Circuit Code entries in the Diagnostic Trouble Codes reference before testing.

2 Cause

The root cause is a worn brush set and degraded voltage regulator inside alternator ALT-8810, which causes erratic field control and trips P0620 as output collapses under demand. As regulated output falls, system voltage drops below threshold and the low-voltage condition is logged. See the Alternator topic in the Charging System Overview for component construction and operating specifications.

3 Repair Procedure

Begin with PROC-CHG-DIAG and the Charging System Diagnosis Procedure to confirm output is below the 180A rated specification and to rule out cabling and ground faults. If the alternator fails the load test, replace alternator ALT-8810 following PROC-ALT and the Alternator Replacement Procedure . Additional service context is available under the Charging System Diagnosis Sub-System and Alternator Sub-System Service . After replacement, clear P0562 and P0620 and verify regulated charging voltage under load.