

"Ridgeline HD 6.7 TD: Diesel particulate filter efficiency below threshold"

Document: tsb-27-111

Area: bulletins

1 Condition

Affected Ridgeline HD 6.7 TD vehicles may set DTC P2002 (Diesel Particulate Filter Efficiency Below Threshold). Drivers may report illuminated check engine and DPF warning lamps, reduced power from a forced derate, and frequent regeneration attempts. Confirm the code against the Emissions Diagnostic Trouble Code Reference and review the DPF Efficiency Faults topic for shared diagnostic logic before proceeding.

2 Cause

The condition is caused by accumulated ash loading and partial substrate degradation in diesel particulate filter DPF-5180, which lowers measured filtration efficiency below the calibrated threshold and sets P2002.

Excessive short-trip operation or repeatedly interrupted regenerations accelerate this loading. See the Diesel Particulate Filter topic and the Emissions System Overview for filter construction and efficiency monitoring details.

3 Repair Procedure

Begin with the emissions system checks in Diagnosis and attempt a service regeneration per PROC-DPF-REGEN using the Diesel Particulate Filter Service and Forced Regeneration procedure. If efficiency does not recover after forced regeneration, replace diesel particulate filter DPF-5180 following the DPF Service and Regeneration guidance. After repair, reset the ash counter, clear P2002, and verify a completed regeneration cycle on a road test.