

Safety Recall - Ignition Coil Internal Arcing and Stall

Document: rc-2021-02

Area: recalls

1 Defect Description

Affected vehicles were built with ignition coil assembly IC-2044-A, in which a manufacturing defect in the secondary winding insulation allows internal arcing under high-load conditions. The arcing produces an intermittent loss of spark on the affected cylinder, setting cylinder-specific misfire code P0351 and, as the condition spreads, the random/multiple misfire code P0300. A severe misfire event can cause a rough idle, hesitation, or an unexpected engine stall while driving, which increases the risk of a crash. Diagnosis of the underlying spark loss should follow the procedures in Falcon Engine Service Manual :: Misfire Diagnosis and the coil-level checks in Heron Ignition Service Manual :: Coil Primary and Secondary Circuit Faults . Technicians should confirm the freeze-frame data against the Harrier Engine Service Manual :: Misfire Diagnostic Trouble Code Reference before condemning the coil.

2 Remedy

Dealers will replace all affected IC-2044-A ignition coils with a redesigned coil featuring improved secondary winding insulation, free of charge. The replacement must follow the removal and torque sequence described in Heron Ignition Service Manual :: Application-Specific Coils , with verification of correct connector seating per Heron Ignition Service Manual :: Ignition Coils . After installation, clear stored codes and road-test to confirm no recurrence of P0351 or P0300, referencing Harrier Engine Service Manual :: Misfire Diagnosis Procedure . Owners can confirm recall applicability and remedy status at <https://www.nhtsa.gov/recalls>.