

Safety Recall - High-Pressure Fuel Pump Leak Fire Risk

Document: rc-2021-03

Area: recalls

1 Defect Description

Affected vehicles were assembled with high-pressure fuel pump HPFP-4120, whose pump body sealing surface may develop a hairline crack that allows pressurized fuel to weep from the GDI delivery circuit. A loss of rail pressure sets the fuel pressure performance code P0087, while a failing or out-of-range pressure sensor signal can set P0190. Fuel leaking onto hot engine components creates a fire hazard, and the loss of pressure can also cause hard starting, stalling, or a sudden loss of motive power. Diagnosis should begin with the pressure verification steps in Osprey Fuel Service Manual :: Fuel Pressure and Sensor Faults and the pump-specific inspection in Osprey Fuel Service Manual :: High-Pressure Fuel Pump (GDI) .

2 Remedy

Dealers will inspect and replace the affected HPFP-4120 high-pressure fuel pump with a revised pump incorporating an upgraded body seal, free of charge. The replacement and rail-pressure relief procedure must follow Osprey Fuel Service Manual :: Fuel Delivery , with post-repair leak-down verification described in Summit Fuel Service Manual :: Fuel Trim and Pressure Diagnosis Procedure . After repair, confirm that P0087 and P0190 do not reset by cross-checking the values in Summit Fuel Service Manual :: Fuel Diagnostic Trouble Code Reference and reviewing system layout in Summit Fuel Service Manual :: Fuel System Overview . Owners can verify recall status at <https://www.nhtsa.gov/recalls>.