

Safety Recall - Lower Control Arm Fracture Loss of Control

Document: rc-2021-08

Area: recalls

1 Defect Description

Affected vehicles may have a lower control arm, part number CARM-8540, manufactured with an inconsistent weld at the rear bushing mount that can develop a fatigue crack under sustained load. If the crack propagates, the control arm can fracture, allowing the wheel to deflect and producing a sudden loss of directional control. The role of this component is described in Ridgeline HD Suspension Service Manual :: Control Arms and Sway Bar Links and the broader Ridgeline HD Suspension Service Manual :: Suspension System Overview . Owners may notice a clunk or wandering steering as an early indicator of a developing crack.

2 Remedy

Dealers must replace the affected lower control arm CARM-8540 on both sides following the Ridgeline HD Suspension Service Manual :: Control Arm Replacement Procedure within the Ridgeline HD Suspension Service Manual :: Control Arm and Sway Bar Sub-System Service . Because the control arm carries the wheel hub bearing WHB-8580, technicians must inspect that bearing for any play or damage incurred during the fracture event using the Ridgeline HD Suspension Service Manual :: Wheel Hub Bearing Replacement Procedure and replace it if necessary. A four-wheel alignment must be performed after the repair, and the full procedure set is referenced in the Ridgeline HD Suspension Service Manual . All work is performed at no charge to the owner.