

Marlin EV front brake hose may rupture reducing braking

Document: rc-2023-04

Area: recalls

1 Defect Description

On affected Marlin EV vehicles, the front brake hose BH-7745 may have been manufactured with an out-of-spec inner liner that swells when exposed to brake fluid over time. As the liner degrades, the hose can balloon or rupture under pressure, releasing brake fluid BF-7790 and reducing hydraulic clamping force at the front calipers. Inspection and replacement should follow Marlin EV Brakes Service Manual :: Hydraulic Lines and Fluid . Technicians familiar with comparable platforms may also reference the Vega Brakes Service Manual :: Front Brake Sub-System for routing and torque context.

2 Safety Risk and Affected Vehicles

A ruptured BH-7745 front brake hose causes a sudden loss of hydraulic pressure at the affected front wheel, increasing stopping distance and the risk of a crash. Affected vehicles are Marlin EV units built within the identified production window using brake hoses from the suspect supplier lot. Drivers may notice a soft or sinking brake pedal, a brake warning indicator, or visible fluid loss near the front wheel. Any vehicle exhibiting these symptoms should be removed from service until inspected per Marlin EV Brakes Service Manual :: Brake Hose Replacement Procedure .

3 Remedy

Authorized dealers will replace both front brake hose BH-7745 assemblies with revised hoses and refill with fresh brake fluid BF-7790, free of charge. Replace the hoses following procedure PROC-BRAKE-HOSE as detailed in Marlin EV Brakes Service Manual :: Brake Hose Replacement Procedure , then perform procedure PROC-BRAKE-FLUID to flush and bleed the system per Marlin EV Brakes Service Manual :: Brake Fluid Flush and Bleed Procedure . Confirm a firm pedal and verify no fluid loss before returning the vehicle to the customer; the Vega Brakes Service Manual :: Brake Fluid Flush and Bleed procedure offers a comparable bleed sequence for reference. Owners should contact their dealer to schedule this no-charge repair.