

Lumen electric power steering motor may lose assist while driving

Document: rc-2023-07

Area: recalls

1 Defect Description

Certain Lumen vehicles were assembled with an electric power steering motor, part number EPS-8740, whose torque-sensor signal can drift out of calibration over time. When the drift exceeds the controller threshold the EPS module sets diagnostic trouble code C1556 and commands a fail-safe that drops steering assist. The Lumen Steering Service Manual :: Electric Power Steering Motor describes the motor and integrated sensor, and the fault behavior is detailed under Lumen Steering Service Manual :: EPS Torque Sensor Fault .

2 Safety Risk and Affected Vehicles

A sudden loss of power steering assist from EPS-8740 substantially increases steering effort and can lead to a crash, particularly during low-speed maneuvers and parking. Affected vehicles are Lumen units within the identified build range; confirm the steering configuration using the Lumen Steering Service Manual and the Lumen Steering Service Manual :: Steering System Overview before beginning work.

3 Remedy

Dealers will reflash and recalibrate the EPS module and, where the torque sensor cannot be brought into specification, replace the motor assembly EPS-8740 at no charge under procedure PROC-EPS-DIAG. Technicians should clear C1556, then validate the repair following the Lumen Steering Service Manual :: Electric Power Steering Diagnosis Procedure within the Lumen Steering Service Manual :: Diagnostic Trouble Codes framework. Owners may check whether their vehicle is included and find remedy details at <https://www.nhtsa.gov/recalls>.