

Vega brake master cylinder seal leak reduces braking performance

Document: rc-2023-12

Area: recalls

1 Defect Description

On affected Vega vehicles, an internal primary seal within the brake master cylinder (part BMC-7780) may swell and allow brake fluid (specification BF-7790) to bypass the piston during pedal application. This internal leak produces a slowly sinking pedal and reduced hydraulic pressure to the calipers, lengthening stopping distance and increasing crash risk. The role and service points of this component are detailed in the Vega Brakes Service Manual :: Hydraulic Sub-System and specifically under Master Cylinder Service . The equivalent component coverage on the shared EV platform appears in the Marlin EV Brakes Service Manual :: Brake Master Cylinder Service .

2 Remedy

Dealers will replace the brake master cylinder (BMC-7780) free of charge and refill the system with fresh fluid meeting specification BF-7790, following repair instruction PROC-BRAKE-FLUID. After replacement the hydraulic system must be fully flushed and bled per the Brake Fluid Flush and Bleed steps to remove contaminated fluid and trapped air. The procedure is consistent with the Brake Fluid Flush and Bleed Procedure under Hydraulic Lines and Fluid . For complete torque and bleed-sequence data, technicians should consult the full Vega Brakes Service Manual .