

"Summit 5.0 V8: C0040 right front wheel speed sensor circuit fault"

Document: tsb-22-343

Area: bulletins

1 Condition

The Summit 5.0 V8 may illuminate the ABS and traction control warning lamps with diagnostic trouble code C0040 stored as current or history. Drivers may report intermittent ABS activation at low speed or loss of stability control function. The code C0040 specifically identifies a circuit fault associated with the right front wheel speed channel. See the Summit Abs Service Manual :: ABS System Overview for lamp behavior and a description of fault-driven function disablement.

2 Cause

Code C0040 sets when the ABS module detects an open, short, or out-of-range signal from the right front wheel speed sensor WSS-3300. Corrosion at the connector, a chafed harness near the strut bracket, or a cracked sensor body are the most common root causes. A contaminated or damaged tone ring will also produce an erratic signal that triggers C0040. Diagnostic decision trees for this fault are in the Summit Abs Service Manual :: Wheel Speed Sensor Circuit Codes , and sensor operating principles are covered in the Summit Abs Service Manual :: Wheel Speed Sensors section.

3 Repair Procedure

Diagnose and replace the right front sensor WSS-3300 following [PROC-WSS] as detailed in the Summit Abs Service Manual :: Wheel Speed Sensor Replacement Procedure . Inspect and repair the harness and connector before installing the new WSS-3300, then route the lead clear of suspension travel. Reference the broader Summit Abs Service Manual :: Wheel Speed Sensor Sub-System Service for air-gap and mounting torque values.

4 Verification

After repair, clear all codes with a capable scan tool and confirm C0040 does not reset. Perform a road test above the ABS arming speed and monitor live wheel speed data to confirm all four channels track together. Reference the Summit Abs Service Manual :: Diagnostic Trouble Codes chapter to confirm no related codes remain pending before releasing the vehicle.