

# "Lumen: Electric power steering torque sensor fault causing loss of assist"

Document: tsb-23-156

Area: bulletins

## 1 Condition

Lumen drivers may report sudden or intermittent loss of power steering assist, with the steering warning lamp illuminated and noticeably heavier effort at low speed. A scan of the EPS module returns DTC C1556 (EPS Torque Sensor Fault), sometimes after a key cycle or over a thermal soak. Assist may temporarily return after restart, masking the condition. For an overview of the assist system, see the Lumen Steering Service Manual :: Steering System Overview .

## 2 Cause

The fault originates in the torque sensor integrated with EPS assembly EPS-8740, where signal drift or an internal short causes the module to disable assist and store C1556. Because the torque sensor is not serviced separately, a confirmed sensor fault requires replacement of the EPS-8740 column assembly. Confirm the diagnosis using Lumen Steering Service Manual :: EPS Torque Sensor Fault and rule out low-voltage causes before replacing parts. The motor and sensor packaging is described in Lumen Steering Service Manual :: Electric Power Steering Motor .

## 3 Repair Procedure

Follow diagnostic procedure PROC-EPS-DIAG to validate the C1556 condition, then replace EPS-8740 and perform the steering angle and torque relearn. The full sequence is documented in the Lumen Steering Service Manual :: Electric Power Steering Diagnosis Procedure ; clear C1556 and verify assist across the full lock range. Sub-system service references are collected under Lumen Steering Service Manual :: Electric Power Steering Sub-System Service .