

"Kestrel: Module configuration failure after headlamp assembly replacement"

Document: tsb-27-114

Area: bulletins

1 Condition

On the Kestrel, technicians may encounter a module configuration failure following replacement of a headlamp assembly, with the body control module setting DTC B2477. The vehicle may exhibit warning lamps, inoperative exterior lighting, or a failed end-of-line configuration. Confirm the stored code against the Kestrel Body Service Manual :: Body Diagnostic Trouble Code Reference and review the Kestrel Body Service Manual :: Module Configuration Failure Diagnosis before proceeding.

2 Cause

DTC B2477 is set when the BCM cannot validate the configuration data for the newly installed headlamp assembly HLMP-7020, typically because the part was fitted without the required module write. The mismatch between the stored configuration and the installed HLMP-7020 triggers the fault and disables affected lighting outputs. The Kestrel Body Service Manual :: Body Electrical System Overview describes how the BCM authenticates lighting components, and the Kestrel Body Service Manual :: Diagnosis outlines the supporting checks.

3 Repair Procedure

Install headlamp assembly HLMP-7020 per PROC-HEADLAMP as detailed in the Kestrel Body Service Manual :: Headlamp Assembly Replacement Procedure , then perform the module configuration per PROC-BCM-CONFIG. Run the configuration using the Kestrel Electrical Service Manual :: BCM Configuration Procedure ; the equivalent cross-platform routine is documented in the Vega Electrical Service Manual :: Body Control Module Configuration Procedure . After configuring HLMP-7020, clear DTC B2477, cycle the lighting, and verify the code does not return. For lighting sub-system context see the Kestrel Body Service Manual :: Lighting Sub-System .