

"Safety Recall - Ignition Coil Connector Overheating"

Document: rc-2021-01

Area: recalls

1 Defect Description

Affected vehicles were built with ignition coil IC-2042-A whose electrical connector can overheat under sustained high-load operation, degrading the coil output. As the connection deteriorates, the engine may misfire and set DTC P0301 (cylinder 1 misfire detected) and, in cases affecting multiple cylinders, DTC P0300 (random/multiple cylinder misfire). A persistent misfire can lead to rough running, a stall risk, and potential catalyst damage. Diagnostic guidance for these codes is provided in the Falcon Engine Service Manual :: Misfire Diagnosis and the Harrier Engine Service Manual :: Misfire Diagnostic Trouble Code Reference . Owners noticing these symptoms should contact a dealer; recall details are posted at <https://www.nhtsa.gov/recalls>.

2 Remedy

Dealers will replace ignition coil IC-2042-A with the redesigned coil IC-2042-B, which incorporates an upgraded connector and improved thermal margin. At the same time, spark plug SP-1108 will be inspected and replaced as required to ensure proper combustion after the coil swap. Coil identification and the IC-2042-A to IC-2042-B supersession are documented in the Heron Ignition Service Manual :: Coil Identification and Supersession , with plug specifications in the Heron Ignition Service Manual :: Spark Plug Selection and Specifications . After installing IC-2042-B and SP-1108, clear any stored P0301 or P0300 and verify per the Harrier Engine Service Manual :: Misfire Diagnosis Procedure . Further ignition reference is available in the Heron Ignition Service Manual :: Ignition Coils .