

Safety Recall - ABS Pump Motor Failure Loss of Anti-Lock Braking

Document: rc-2021-07

Area: recalls

1 Defect Description

Affected vehicles are equipped with an electronic brake control module assembly, part number EBCM-8100, whose integrated hydraulic pump motor may seize due to brush wear. When the motor fails, the module disables anti-lock and stability functions and stores diagnostic trouble code C0110 for the pump motor circuit, frequently accompanied by C0265 indicating a pump motor relay circuit fault. The pump and relay circuit behavior is detailed in the Summit Abs Service Manual :: Pump and Relay Circuit Codes and the related Summit Abs Service Manual :: Diagnostic Trouble Codes . Base hydraulic braking is retained, but the loss of anti-lock control increases stopping distances on low-traction surfaces. Background on the affected assembly is provided in Summit Abs Service Manual :: ABS Hydraulic Pump Assembly .

2 Remedy

Dealers must replace the electronic brake control module EBCM-8100 as a complete assembly, since the pump motor is not serviceable separately, following the Summit Abs Service Manual :: ABS Module Diagnosis Procedure to confirm the failure before replacement. Removal and installation are covered under Summit Abs Service Manual :: EBCM and Hydraulic Sub-System Service , and module identification is described in Summit Abs Service Manual :: Electronic Brake Control Module (EBCM) . After installation the replacement module must be programmed and the system bled, then verified clear of stored codes. The repair is performed at no cost to the owner; see the Summit Abs Service Manual for full procedure references.