

Lumen electric power steering motor may fail and cause sudden loss of steer

Document: rc-2022-03

Area: recalls

1 Defect Description

On certain Lumen vehicles, a winding insulation defect in the electric power steering motor, part number EPS-8740, can cause an internal short under sustained high-load steering. When the controller detects the abnormal motor signal it sets DTC C1556 (EPS Torque Sensor Fault) and disables power assist to protect the system. The driver experiences a sudden increase in steering effort, which is most hazardous during low-speed parking maneuvers and tight turns. The Electric Power Steering Motor and its operation are described in the Steering System Overview of the Lumen Steering Service Manual , and the fault is detailed under EPS Torque Sensor Fault .

2 Remedy

Dealers will replace the EPS-8740 steering motor assembly with an improved unit free of charge and clear the stored C1556 code. Technicians must perform the Electric Power Steering Diagnosis Procedure to verify the fault originates in the motor and not in the torque sensor harness before replacement. Full removal and calibration steps are provided in the Electric Power Steering Sub-System Service section. Owners should contact their dealer to arrange the repair at no cost.