

Osprey 3.5 V6 high-pressure fuel pump seal degradation can cause fuel leak a

Document: rc-2022-04

Area: recalls

1 Defect Description

On affected Osprey 3.5 V6 vehicles, the high-pressure fuel pump, part number HPFP-4120, uses an internal seal that can degrade with exposure to ethanol-blended fuel. As the seal hardens it loses sealing pressure, which causes a measurable drop in rail pressure and sets DTC P0087 (Fuel Rail/System Pressure Too Low). A degraded seal can also weep fuel onto hot engine components, creating an underhood fire risk. The High-Pressure Fuel Pump (GDI) is documented in the Fuel Delivery chapter of the Osprey Fuel Service Manual , with diagnostic detail under Fuel Pressure and Sensor Faults .

2 Remedy

Dealers will replace the HPFP-4120 high-pressure fuel pump with a revised assembly using an ethanol-resistant seal at no charge. Before condemning the pump, technicians should follow the Fuel System Diagnosis routine to confirm P0087 is caused by the pump rather than a clogged filter or failed pressure sensor. After replacement the rail must be pressure-tested for leaks and the trouble code cleared. Owners should contact their dealer to schedule the free repair as soon as possible given the fire risk.