

Vega front brake caliper piston seizure can cause brake drag, overheating, and

Document: rc-2022-08

Area: recalls

1 Defect Description

Certain Vega vehicles were built with front brake calipers (part BCAL-7760) whose piston bore can corrode and cause the piston to seize in the applied position. A seized BCAL-7760 caliper keeps the front brake pads (part BP-7720) in constant contact with the rotor, producing brake drag, excessive heat, and premature wear of BP-7720. Prolonged dragging degrades braking performance and, in extreme cases, can damage adjacent components. Inspection criteria for the front corner are described in the Vega Brakes Service Manual :: Front Brake Sub-System and the Vega Brakes Service Manual :: Caliper Sub-System .

2 Remedy

Dealers will replace the affected front caliper BCAL-7760 and the associated front brake pads BP-7720 at no charge to the owner. Replace the caliper following the Vega Brakes Service Manual :: Brake Caliper Replacement , then service the friction material per the Vega Brakes Service Manual :: Front Brake Pad Replacement . After installing BCAL-7760 and BP-7720, bleed the system and confirm the pads release freely with no residual drag, referencing the Vega Brakes Service Manual :: Front Brake Pad and Rotor Service . The complete repair reference is the Vega Brakes Service Manual ; owners will be notified by mail and recall information is available at <https://www.nhtsa.gov/recalls>.