

Vega underhood fuse box corrosion can cause electrical failure and fire

Document: rc-2023-08

Area: recalls

1 Defect Description

Certain Vega vehicles have an underhood fuse box, part number FUSE-9980, with an inadequate weather seal that allows moisture intrusion and terminal corrosion. The corrosion raises resistance and intermittently interrupts power and CAN distribution, which can set lost-communication codes U0100 and U0140 and, in severe cases, generate localized heating and fire. The fuse box and its harness interfaces are documented in the Vega Electrical Service Manual :: Wiring Harness and Fuse Box , with code definitions under Vega Electrical Service Manual :: Lost Communication with ECM/PCM and Vega Electrical Service Manual :: Lost Communication with BCM and Cluster .

2 Safety Risk and Affected Vehicles

Corrosion-induced failure of FUSE-9980 can cause unexpected loss of electrical functions, stalling, and underhood fire, creating a crash and injury hazard. Affected vehicles are Vega units within the identified production period; review the Vega Electrical Service Manual and the Vega Electrical Service Manual :: Electrical System Overview to confirm the electrical architecture before inspection.

3 Remedy

Dealers will replace the underhood fuse box FUSE-9980 with a sealed-design service part at no charge and verify network integrity per procedure PROC-COMMS-DIAG. After replacement, clear U0100 and U0140 and confirm bus health using the Vega Electrical Service Manual :: CAN Bus Communication Diagnosis Procedure and the wiring references in Vega Electrical Service Manual :: Wiring Diagrams and Reference . Owners can confirm recall applicability and remedy status at <https://www.nhtsa.gov/recalls>.