

Summit in-tank fuel pump may fail causing engine stall

Document: rc-2023-11

Area: recalls

1 Defect Description

On affected Summit vehicles, the in-tank low-pressure fuel pump (part FP-4100) may experience premature brush wear that intermittently interrupts fuel delivery to the high-pressure circuit. As supply pressure drops, the engine control module sets DTC P0087 (fuel rail/system pressure too low) and the engine may hesitate, lose power, or stall without warning, increasing crash risk. The construction and rated output of this component are described in the Summit Fuel Service Manual :: Fuel System Overview . A stored P0087 should be cross-checked against the Fuel Diagnostic Trouble Code Reference before any parts are condemned, using the broader Diagnosis workflow.

2 Remedy

Dealers will replace the in-tank fuel pump (FP-4100) free of charge following repair instruction PROC-FUEL-PUMP, which mirrors the equivalent Fuel Pump Replacement Procedure for the shared module platform. Before and after replacement, technicians must verify supply pressure and fuel trim per PROC-FUEL-DIAG, following the Fuel Trim and Pressure Diagnosis Procedure and confirming no residual Fuel Pressure and Sensor Faults . For the underlying delivery architecture, see Low-Pressure Fuel Pump and the complete Summit Fuel Service Manual .