

Updated Catalyst Monitor Calibration

Document: tsb-20-087

Area: bulletins

1 Condition

Falcon and Osprey vehicles may set catalyst code P0420 with no driveability complaint and a catalyst that tests within spec. An over-sensitive monitor calibration is the cause in these cases.

2 Cause

The previous ECM-9901 calibration flags marginal catalyst readings too aggressively, producing false P0420 reports.

3 Repair Procedure

Apply the updated ECM-9901 calibration per ECM Software Updates before replacing any CAT-5500 catalytic converter. Confirm there is no active misfire first — see Catalyst Efficiency .