

Revised Ignition Coil for Repeated Misfire

Document: tsb-21-114

Area: bulletins

1 Condition

Some 2019-2021 Falcon vehicles with the 2.0T engine exhibit repeat misfire codes P0301 or P0300 after a coil has already been replaced. For the baseline diagnostic routine, see Misfire Diagnosis .

2 Cause

The original ignition coil IC-2042-A insulation can degrade under repeated heat cycles, causing intermittent misfire that returns after replacement with the same part.

3 Repair Procedure

Replace all coils with the revised ignition coil IC-2042-B, which supersedes IC-2042-A, following Ignition Coil Replacement . Replace spark plug set SP-1108 if beyond half service life. The connector failure mode is also addressed by safety recall RC-2021-04 .