

Brake Judder After Front Pad Replacement

Document: tsb-22-031

Area: bulletins

1 Condition

Falcon and Osprey vehicles may exhibit steering-wheel judder under braking shortly after a front brake pad change. Affected parts are the BP-7720 pad kit and BR-7731 rotor pair.

2 Cause

Reusing rotors beyond runout spec, or machining the BR-7731 (not approved), leaves thickness variation that produces judder.

3 Repair Procedure

Replace the BR-7731 rotor pair together with the BP-7720 pads; do not machine. Follow Front Brake Service and torque to spec. Inspect the BH-7745 brake hose while the caliper is off.