Lab 4h Stepper Motor Finite State Machine

This laboratory assignment accompanies the book, Embedded Microcomputer Systems: Real Time Interfacing, Second edition, by Jonathan W. Valvano, published by Thomson, copyright © 2006.

Goals • To interface a stepper motor,

• To implement background processing with periodic interrupts,

• To develop a dynamic linked command structure.

Review • Valvano Section 1.4 about open collector logic,

• Valvano Chapter 2 about abstraction, linked lists and FSM's,

• Valvano Chapter 8, about stepper motor interfacing,

• Valvano Section 13.2.3, about an open loop stepper motor control system.

Starter files • Moore_DP512.zip OC_DP512.zip projects and

• the PCBArtist file Lab4h_Artist.sch

Background

Stepper motors are popular with digital control systems because they can be used in an open loop manner with predictable responses. Such applications include positioning heads in disk drives, adjusting fuel mixtures in automobiles, and controlling articulating joints in robotics. In this lab, you will control a stepper motor using a finite state machine. The finite state machine must be implemented as a linked data structure. Four switches will allow the operator to control the motor. A background periodic interrupt (either OC or RTI) thread will perform inputs from the switches and outputs to the stepper motor coils. The worm gear on the motor, as shown in Figure 4.1, produces a linear motion as the stepper motor turns. It takes 24 full-steps to complete one rotation of the shaft and 200 full-steps to move the worm gear from one end to the other. If you step the motor too far in either direction, the worm gear will disengage and you will have to manually re-engage the worm gear. Three switches determine the motor operation.

If all buttons are released, then the motor should stop.

While switch 1 is held down, spin slowly (switch 2 determines the direction). I.e.,

If switch 1 and not switch 2, spin slowly in the other direction.

If both switch 1 and switch 2, spin slowly in the other direction.

If switch 2 is pressed then released (but not switch 1) then step once in one direction on the release of 2.

If switch 3 is pressed, the motor should continuously vibrate as fast as possible back and forth

CW for 7 steps and CCW for 7 steps as long as switch 3 continues to be pressed.

You should choose time delays to minimize jerk.

Any other combination (e.g., 1+3, 2+3, 1+2+3, etc.) should be ignored.

You may assume the operator (you or the TA) will release the switches when it reaches the end of the worm gear.



Figure 4.1. Stepper motor with worm gear, CAT# EX-82, http://www.allelectronics.com.

Preparation (do this before your lab period)

With an ohmmeter, measure the resistance of one coil. Apply +5V across the coil and simultaneously measure using both a voltmeter and a current-meter the voltage and current required to activate one coil of your

stepper motor. Do this before your lab period, without any connections to the 9S12 board. Design the hardware interface between the 9S12, and prepare a circuit diagram labeling all resistors and diodes. The pin out for the stepper is shown in Figure 4.2. Include pin numbers and resistor/capacitor types and tolerances. Be sure the interface circuit (e.g., 2N2222 or L293) you select can sink enough current to activate the coil. In particular, verify the driver can supply (I_{CE} or I_{OL}) the required current for the stepper motor. Make sure you have all the parts you need before lab starts. This interface will require four 1N914 snubber diodes. If do not properly connect the diodes, the back EMF will destroy your board.




Figure 4.2. The EX-82 stepper motor has unipolar configuration with four+5V 37- Ω coils (see the starter file Lab4h_Artist.sch).

Design the machine by first drawing the finite state graph. A "syntax-error-free" hardcopy listing for the software is required as preparation. This will be checked off by the TA at the beginning of the lab period. You are required to do your editing before lab. The debugging will be done during lab. Document clearly the operation of the routines. The periodic interrupt-driven background thread will execute the finite state machine, while the foreground thread initializes the system then does nothing. Figure 4.3 shows the data flow graph of the stepper motor controller.




Figure 4.3. Data flows from the timer and the switches to the stepper motor.

Figure 4.4 shows a possible call graph of the system. Dividing the system into modules allows for concurrent development and eases the reuse of code.





Page 4h.3




Figure 4.4. A call graph showing the three modules used by the stepper controller.

A switch device driver means you create **switch.h** and **switch.c** files, separating mechanisms (how it works) from policies (what it does). Similarly, make **stepper.h** and **stepper.c** files. Design the software in a manner that makes it easier to understand, debug, modify and reuse in other projects. Design the system in a manner that would allow you to reassign the pin connections of the interface (e.g., moving the stepper from **PTH** to **PTP**), by making changes to **switch.c** and **stepper.c** without requiring modifications to **main.c switch.h** or **stepper.h**.

Procedure (do this during your lab period)

Make sure your TA checks your hardware diagram before connecting it to the 9S12. We do not have extra boards, so if you fry your board, you may not be able to finish. First build the digital interface on a separate protoboard from the 9S12, as shown in Figure 4.5. Use switches as inputs for the stepper interface. You should be able to generate the 5,6,10,9 sequence with your fingers. Using a scope, look at the voltages across the coils to verify the diodes are properly eliminating the back EMF. The very fast turn-off times of the digital transistors can easily produce 100 to 200 volts of back EMF, so please test the hardware before connecting it to the 9S12.




Figure 4.5. Hardware test procedure.

The switches will eventually be replaced by 9S12 outputs, as shown in Figure 4.6. Once you are sure the hardware is operating properly, run a simple software function that rotates the motor at a slow but constant velocity to verify the hardware/software interface.




Figure 4.6. Hardware block diagram.

To determine the fastest rate the motor can vibrate back and forth (CW for 7 steps and CCW for 7 steps), experimentally test the system at smaller and smaller delays between steps. You will be able to vibrate more quickly using a non-uniform time delay between steps. Read the discussion of jerk in Chapter 8 of the textbook.

Remove the wall wart power cable and carefully power your stepper motor system using a lab power supply (not on the +5V pin on the protoboard but the 2-pin male header labeled J1-PWR on the board itself). Set the voltage to +6V and measure the required current to run the stepper motor. Take a measurement with and without the motor spinning. Double check the positive and negative connections before turning it on. If you are at all unsure about this measurement ask your TA for help.

Deliverables (exact components of the lab report)

- A) Objectives (1/2 page maximum)
- B) Hardware Design (PCB Artist printout)

stepper motor interface, showing all external components

switch interfaces, showing all external components

C) Software Design (a hardcopy software printout is due at the time of demonstration)

Draw figures illustrating the major data structures used, e.g., the finite state graph

If you organized the system different than Figure 4.3 and 4.4, then draw its data flow and call graphs

D) Measurement Data

Prep) Give the voltage, current, and resistance measurements

Specify the fastest rate the motor can vibrate back and forth

Measurements of current required to run the system, with and without the motor spinning

- E) Analysis and Discussion (give short 1 or two sentence answers to these questions)
- 1) What is jerk? How is it minimized?
- 2) Draw an electrical circuit model for one stepper motor coil, and explain the components.
- 3) Explain what parameters were important for choosing a motor drive interface chip (e.g., L293 or 2N2222). How does your circuit satisfy these parameters?
- 4) Why does the regulator get hot, even when the motor is not spinning?
- 5) It the motor is spinning at a constant rate, give a definition of electrical power in terms of parameters of this lab? Research mechanical power. Give a definition of mechanical power. Are the two related?

Checkout (show this to the TA)

You should be able to demonstrate correct operation of the stepper motor system. Be prepared to describe how your stepper interface works. Explain how your system handles the switch bounce. Demonstrate debugging features that allow you to visualize the software behavior.

A pdf file of your software must be uploaded, and graded for style at a later time.

Hints

- 1. Be sure the interface driver (e.g., the 2N2222 or L293) has an I_{CE} or I_{OL} large enough to deliver the needed coil current. Although many steppers will operate at voltages less than the rated voltage, the torque is much better when using the proper voltage. Remember to actually measure the coil current rather than dividing voltage by resistance.
- 2. Be sure to put an appropriate delay between each step to prevent the motor from burning up.
- 3. The 9S12DP512 +5V regulated supply is specified to 100 mA total current. Your motor requires about twice this value. To prevent the power supply from overheating, do not leave the system plugged in too long. Even while stopped the stepper draws current. So, you will notice the 9S12 regulator will get hot.
- 4. The **TExaS** simulator does include a stepper motor, so you can develop and test the software in parallel with the hardware development. In particular, the **OC** project can be run on the **TExaS** simulator.
- 5. You are done if

there is a 1-1 mapping from the FSM graph and the C data structure

it is a FSM with 3 inputs and 4 outputs

there is a delay for each state, which is saved in the FSM structure

the motor output is always one of these values 5, 6, 10, or 9

the motor moves such that the output never skips from 5 to 10, 10 to 5, 6 to 9, or 9 to 6

there are about 20 to 30 states, and it works approximately the way it is described in the lab assignment

the FSM runs in the background using periodic interrupts

the foreground (main) initializes the FSM, then executes for (;;) {} do nothing loop

the ISR has no backward jumps. i.e., there are no wait function calls in the ISR

6. See the data sheets and materials on stepper motors at

http://users.ece.utexas.edu/~valvano/DataSheets/

2N2222.pdf L293.pdf

1N914.pdf B3F-1059.pdf, B3F-switch.pdf

Stepper.pdf

StepperBasic.pdf StepperDriveBasic.pdf StepperHalfstep.pdf StepperSelection.pdf Stepper_ST.pdf