

REF NO	EVENT	HAZARD	Consequence (Worst case scenarios)	Existing Controls	Risk			Mitigation Action	Own ershi p	New Controls	Risk		
					Probability	Severity	Rating				Probability	Severity	Rating
1	GSE Fault • Technical fault in passenger bus number 67, due to damage to the clip (or clamp) used for water storage.	• The bus water clamp is damaged causing potential leakage of water	• Water leakage that could lead to employees or passengers slipping • Delay in passenger boarding due to a shortage of available buses	•			Moderate	Corrective Actions: • Repair the clip and replace it with a higher-quality component. • Inspect all other buses for the same fault. • Review maintenance procedures to ensure the early detection of minor faults.		Preventive Actions: • Update maintenance schedules to include inspection of all water tank components and related systems. • Provide a standby bus ready at each departure gate. • Train drivers and technicians to report minor leaks immediately. Additional Recommendations: • Please address the root cause, which is the absence of effective periodic preventive inspection for minor bus components. • Ensure a nearby standby bus is available to cover emergency breakdowns.			Moderate
2	Baggage Containers • Loading containers with minor to moderate defects.	• Use of defected baggage containers	• It is Potential that such containers to get stuck in the aircraft causing (damage to the aircraft) • Work delays	•	C	3	3C Acceptable based on risk mitigation. Management decision is required	• FOLLOW-UP : Container supervisor follow-up – to repair damaged ones.		•	E	2	2E Acceptable
3	Baggage Belt : • Some workers and operators are speeding up the baggage belt to expedite unloading the luggage	• Improper use of the baggage belt	• Luggage falling and getting damaged. • Causing damage to the aircraft's fuselage	•	C	3	3C Acceptable based on risk mitigation. Management decision is required	• Raising the awareness of the operator or worker about the danger / risk		•	C	2	2C Acceptable based on risk mitigation. Management decision is required
4	Staff Behavior			•	B	3	3B			•	B	2	2B

REF NO	EVENT	HAZARD	Consequence (Worst case scenarios)	Existing Controls	Risk			Mitigation Action	Ownership	New Controls	Risk		
					Probability	Severity	Rating				Probability	Severity	Rating
SAH-Apr 2025	• Some workers and operators don't wear the safety shoes	• Non-compliance to wear the safety shoes	• Injuries to the staff				Acceptable based on risk mitigation. Management decision is required	• Raising awareness : The worker and operator were apprised of the risks of disregarding safety guidelines and were cautioned against repeated violations					Acceptable based on risk mitigation. Management decision is required
5	Trolleys and Containers Maintenance • Neglecting Lubrication of Luggage Carts and Container Dollies	• Neglecting Lubrication of Luggage Carts and Container Dollies	• Injuries to personnel • Difficulties in use and movement • Increased friction and wear • Noise • Shorter lifespan • Higher operational costs	•	C	4	4C Acceptable based on risk mitigation. Management decision is required	• Raising Awareness: Dealing with Faulty Equipment: • Educating the operator or worker to avoid dealing with faulty equipment • Informing the direct supervisor • Escalating the problem to safety management		•	C	3	3C Acceptable based on risk mitigation. Management decision is required
6	Foreign Object Debris (FOD) : Presence of debris, gravel, stones, or plastic/metal cans near aircraft engines.	• FODs around the aircraft areas— that could be ingested by the engine during operation	• Significant damage to the engine during operation. • Threat to the safety of aircraft, passengers, and staff.	•	B	5	5B Intolerable	CAUTION : There must be work on • Cleaning the apron generally of any of the mentioned items. • Specifically cleaning the aircraft's vicinity of objects that could be ingested by the engine during operation. •		•	E	3	3E Acceptable
7			•	•				•		•			

REF NO	EVENT	HAZARD	Consequence (Worst case scenarios)	Existing Controls	Risk			Mitigation Action	Ownership	New Controls	Risk		
					Probability	Severity	Rating				Probability	Severity	Rating
SAH-Apr 2025	SAFETY CONES— Shortages and Deterioration * Significant shortage of cones. * Poor condition of existing safety vests and deterioration of the reflective tape on most vests. * Repetition of the risk from the first quarter.	SAFETY CONES— Shortages and Deterioration											
8 SAH-Apr 2025	Containers Securing • Empty containers were not secured on the apron, leading to one being moved by the wind into the middle of the apron.	• Unsecured Empty Containers on the Apron	• Severe damage to aircraft. • Collisions • Disruption of operations. • Damage to the company's reputation.	•	C	3	3C Acceptable based on risk mitigation. Management decision is required	• The container was returned and secured onto one of its dedicated dollies. • A risk analysis report was prepared and submitted to the company's Operational Safety Manager. <i>Recommendations</i> -Establish clear lines and markings, especially in relevant areas and near the maintenance hangar. -Foster practical cooperative coordination to assess and implement suitable practical solutions for existing risks.		•	D	3	3D Acceptable based on risk mitigation. Management decision is required
9				•	B	4	4B			•	C	2	2C

REF NO	EVENT	HAZARD	Consequence (Worst case scenarios)	Existing Controls	Risk			Mitigation Action	Ownership	New Controls	Risk		
					Probability	Severity	Rating				Probability	Severity	Rating
SAH-Apr 2025	Passenger Stairs Bus Safety Procedures • Operator Non-Compliance with Apron Safety Procedures for Passenger Stairs Service	• Non-Compliance with Safety Procedures regarding Passenger Stairs Service	• Severe damage to aircraft. • Work disruption. • Injuries to staff and passengers • Operational delays • Reputation Damage				Intolerable	The recommendation was made and escalated to both: the Equipment Department Manager and the Direct Supervisor, regarding • The necessity of not repeating the violation • The importance of holding a refresher course in service delivery, Recommendations • Direct oversight and supervision by the Equipment Department Manager and operations supervisors over operators. • Awareness campaigns and training courses for operators.					Acceptable based on risk mitigation. Management decision is required
10 SAH-Apr 2025	Weather Conditions • Rushing to perform tasks during inclement weather (rainfall) (by Air Catering, Fuel Management, and Equipment Operators) and their weak adherence to safety procedures.	• Rushing to Perform Tasks During Weather (Rainfall)	• Accidents and damages. • Damage to the company's reputation. •	•	D	5	5D Acceptable based on risk mitigation. Management decision is required	• The recommendation was escalated to all three parties: Air Catering Management, Fuel Management, and Equipment Operators, with an emphasis that safety comes first.		•	E	2	2E Acceptable

REF NO	EVENT	HAZARD	Consequence (Worst case scenarios)	Existing Controls	Risk			Mitigation Action	Own ershi p	New Controls	Risk		
					Probability	Severity	Rating				Probability	Severity	Rating

© Risks & Categories

المخاطر وتصنيفاتها



RISK REGISTRY													
II 4 A		Operation Safety Reporting System				تقييم المخاطر				SQAD 2nd Q 2025		1 SAH 2	
PART Article ISSU		Risk Assessment Report											
م.		النشاط		المخاطر المحتملة		تقييم المخاطر		استراتيجية التخفيف		تقييم المخاطر بعد التخفيف			
		APRIL 2025											
		في صباح الإثنين 82 أبريل 8282 ، وأثناء تحميل ركاب رحلة 248 المتجهة من عمان إلى صنعاء (طائرة A320 ، تسجيل AFA) ، تعرض باص المسافرين رقم 67 لعطل ميكانيكي يتمثل في تلف "الكليب" الخاص بخزان الماء، مما أدى إلى تسرب الماء وتعطل الباص بجانب بوابة المغادرة .حاول المهندسان حاتم وسلطان إصلاح الباص في الموقع، ولكن دون جدوى، مما استدعى سحبه إلى الورشة .وقد أدى ذلك إلى تأخر الرحلة بسبب النقص المؤقت في عدد الحافلات المتاحة لنقل الركاب.											
١		عطل فني في باص نقل الركاب رقم ٦٧ ، وذلك بسبب تلف الكليب الخاص بتخزين الماء		تسرب مياه قد يؤدي إلى انزلاق الموظفين أو الركاب. تأخر في تحميل الركاب بسبب قلة الباصات المتاحة.		متوسط		الإجراءات التصحيحية : إصلاح الكليب واستبداله بمكون أكثر جودة. فحص جميع الباصات الأخرى لنفس العطل. مراجعة إجراءات الصيانة لضمان اكتشاف الأعطال الدقيقة مسبقًا. إجراءات وقائية : تحديث جداول الصيانة لتشمل فحص جميع أجزاء خزانات المياه والأنظمة ذات الصلة. توفير حافلة احتياطية جاهزة لكل بوابة مغادرة. تدريب السائقين والفنيين على الإبلاغ الفوري عن التسريبات البسيطة. يرجى معالجة السبب الكائن المتمثل في غياب الفحص الوقائي					

REF NO	EVENT	HAZARD	Consequence (Worst case scenarios)	Existing Controls	Risk			Mitigation Action	Own ershi p	New Controls	Risk		
					Probability	Severity	Rating				Probability	Severity	Rating
			الدوري الفعال لمكونات الحافلة الدقيقة. ○ توفر حافلة احتياطية قريبة لتغطية العطل الطارئ.										
	2E		○ متابعة مسؤول الحاويات- بإصلاح المتضرر منها	3C		○ إمكانية تعلق هذه الحاويات في الطائرة (أضرار بالطائرة) ○ تأخير العمل		تحميل حاويات ذات عيوب تتراوح من صغيرة إلى متوسطة ◀ تكرار من الربع الأول					٢
	2C		○ توعية المشغل أو العامل بخطورة ذلك	3C		○ سقوط العفش وتضرره ○ إلحاق الضرر بجسم الطائرة		تسريع بعض العمال و المشغلين لسير البطة لتعجيل إنزال العفش ◀ تكرار من الربع الأول					٣
	2B		○ تم توعية العامل و المشغل بخطورة تجاهل إرشادات السلامة وتم تحذيرهم من تكرار المخالفة	3B		○ تضرر العامل أو المشغل		عدم إرتداء بعض العمال والمشغلين لأحذية السلامة ◀ تكرار من الربع الأول					٤
	3C		○ توعية المشغل أو العامل بتجنب التعامل مع المعدة المعيوبية وإبلاغ المشرف المباشر والرفع بالمشكلة إلى إدارة السلامة	4C		○ إلحاق الضرر بالمشغل أو العامل صعوبة التعامل مع عربيات العفش		إهمال تزييت عربيات العفش وعربيات الحاويات ◀ تكرار من الربع الأول					٥
	3E		يجب العمل على : ○ تنظيف المرسى بشكل عام من أي من ما تم ذكره ○ وتنظيف محيط الطائرة بشكل خاص من الأشياء التي يمكن ان يسحبها المحرك اثناء التشغيل	5B		○ اضرار كبيرة للمحرك اثناء التشغيل ○ تهديد لسلامة الطائرات والركاب والموظفين		(FOD) وجود مخلفات أو حصى (كري) أو احجار أو علب بلاستيكية او معدنية بالقرب من محركات الطائرة					٦
			○					نقص كبير في الأقماع وتردي حاله الكنزات الموجودة وتهالك الشريط الفسفوري لأغلبه الكنزات ◀ تكرار من الربع الأول					٧
	3D		○ تم القيام بإرجاع الحاوية وتأمينها على إحدى العربات الخاصة بها	3C اعتمادا على استراتيجيات تخفيف المخاطر واتخاذ اقرار		تضرر للطائرات والمعدات والكادر نتيجة : ○ اصطدام الحاويات بالطائرة ○ اصطدام الحاويات بالمعدات ○ جروح خطيرة		عدم تأمين الحاويات الفارغة في المرسى مما تسبب في تحريك الرياح لإحدى الحاويات حتى وصلت بها إلى وسط المرسى					٨

REF NO	EVENT	HAZARD	Consequence (Worst case scenarios)	Existing Controls	Risk			Mitigation Action	Own ershi p	New Controls	Risk		
					Probability	Severity	Rating				Probability	Severity	Rating
			- عمل تقرير تحليل مخاطر والرفع به إلى مدير السلامة التشغيلية بالشركة - توصيات : - عمل خطوط وعلامات لا سيما في المناطق المعنية وكذلك القريبة من هجر الصيانة - التسيق التعاوني عملياً في سبيل تقييم وتنفيذ حلول عملية ملائمة لما هو قائم من المخاطر										
		2C	- تم الرفع والتوصية إلى ضرورة عدم تكرار المخالفة وضرورة عقد دورة تنشيطية في مجال تقديم الخدمة ، إلى كلاً من : مدير قسم المعدات والمشرف المباشر - توصيات : - الرقابة والإشراف المباشر من قبل مدير قسم المعدات ومشرفي التشغيل على المشغلين ، والتوعية وعقد دورات تدريبية لهم	4B		- ضرر بالغ للطائرات - إرباك العمل - تشويه لسمعة الشركة	عدم التزام مشغل المعدات بإجراءات سلامة المرسى الخاصة بتقديم خدمة درج المسافرين		٩				
		2E	- تم الرفع والتوصية لكل من الجهات الثلاث : إدارة التموين الجوي - إدارة الوقود - مشغلي المعدات - التنبيه بأن السلامة أولاً	5D	- احتمالية حصول حوادث وأضرار - تشويه لسمعة الشركة	الإستعجال بتنفيذ المهام أثناء سوء الأحوال الجوية (هطول الأمطار) من قبل التموين الجوي وإدارة الوقود ومشغلي المعدات) وضعف التزامهم بإجراءات السلامة		١٠					